

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 07 Feb 2023

Preliminary Advice

Vehicle No	: SMV8865Z	Accident Date	: 21/01/2023
Make	: PORSCHE 718 CAYMAN (982)	Policy No.	: DMPCSNW00103592201
Assignment Date	: 03/02/2023	Excess	: S\$4,000.00
Date of Inspection	: 06/02/2023	Est. Duration of Repair	: 21
Inspection At	: TEAM AUTOCARE PTE LTD (HQ) 160 SIN MING DRIVE #02-12, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	155,369.20
Revised Amount	:S\$	81,871.30
Check Items (Estimated)	:S\$	27,890.89
Total	:S\$	109,762.19
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	146,000.00
COE / PARF Rebate	:S\$	24,982.00
Salvage Value	:S\$	
Margin for Repair	:S\$	121,018.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY ADVISE THE BODY KIT WITH INSURER POLICY?
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.