

# KAIZEN MOTORS

KAIZEN MOTORS PTE. LTD. UEN: 201502816H  
68 Kaki Bukit Avenue 6, #02-12 Ark@KB, Singapore 417896  
Tel: (+65) 6384 1956 Fax: (+65) 6384 1957  
Webpage: <https://www.kaizenmotors.com.sg>

 kaizenmotorsingapore

 kaizen\_motors

 kaizenmotors

Date : 10/02/2023

Vehicle No : SLE1532G

Model : Toyota Estima

Chassis :

Requesting for List Price

not allowed  
8/1/23  
d/s \$ 1900  
3 days

| No | Job Description                                                                                                                                                                                  | Qty                 | Price / Unit | Amount      |
|----|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|--------------|-------------|
| 1  | REAR BUMPER <i>55/be</i>                                                                                                                                                                         | 1                   | \$ 1,427.40  | \$ 1,427.40 |
| 2  | REAR BUMPER SIDE RETAINER <i>ner</i>                                                                                                                                                             | 1                   | \$ 110.41    | \$ 110.41   |
| 3  | REAR BUMPER REFLECTOR <i>su</i>                                                                                                                                                                  | 1                   | \$ 136.80    | \$ 136.80   |
| 4  | REAR R/H TAIL LAMP <i>27</i>                                                                                                                                                                     | 1                   | \$ 893.50    | \$ 893.50   |
| 5  | REAR R/H TOW COVER <i>27</i>                                                                                                                                                                     | 1                   | \$ 65.50     | \$ 65.50    |
| 6  | REAR BUMPER CLIPS <i>ner</i>                                                                                                                                                                     | 1 set <del>10</del> | \$ 6.00      | \$ 60.00    |
| 7  | REAR REVERSE SENSOR <i>shoked</i>                                                                                                                                                                | 1 set <del>2</del>  | \$ 200.00    | \$ 400.00   |
| 8  | LABOUR FOR CHECKING ON WIRING                                                                                                                                                                    |                     | \$ 150.00    | \$ 150.00   |
| 9  | LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING CUTTING OFF, WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE OF REAR R/H SLIDING DOOR, REAR R/H FENDER, REAR BUMPER |                     | \$ 2,950.00  | \$ 2,950.00 |
| 10 | SPRAYPAINTING & PUTTY OF REAR BUMPER, REAR R/H FENDER, REAR R/H SLIDING DOOR                                                                                                                     |                     | \$ 1,500.00  | \$ 1,500.00 |

781.10

x

x

x

50 S/W

200 S/W

20

540

900

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-891-57

Sub-Total \$ 7,693.61