

Date: 02/02/2023

Vehicle No: SMK2598S

Model: TOYOTA VOXY HYBRID 1.8V CVT

Chassis: ZWR800352553-2018

Reg.Year: 2019

Third Party Insurer:

Third Party Veh No:

Date of Accident:

Estimator:

Surveyor:

AIG

SLH7765X

31/01/2023

TING AN

*Not Authorised
11 Png &*

*Recovery After Paving
7 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		R \$857.00
2	FRONT BONNET HINGE LH	1		R \$90.00
3	FRONT BONNET HINGE RH	1		R \$90.00
4	FRONT GRILLE	1		R \$1,033.00
5	FRONT HEADLAMP LH	1	mg	Br \$2,044.00
6	FRONT HEADLAMP RH	1		R \$2,044.00
7	FRONT HEADLAMP GARNISH COVER LH	1		Dis \$88.00
8	FRONT HEADLAMP GARNISH COVER RH	1		R \$88.00
9	FRONT BUMPER	1		cm \$1,593.00
10	FRONT BUMPER REINFORCEMENT	1		R \$321.00
11	FRONT BUMPER ABSORBER FOAM	1		R \$88.00
12	FRONT BUMPER SIDE BRACKET LH	1		R \$98.00
13	FRONT BUMPER SIDE BRACKET RH	1		R \$98.00
14	FRONT BUMPER FOG LAMP CHROME MOULDING LH	1		R \$158.00
15	FRONT BUMPER FOG LAMP CHROME MOULDING RH	1		R \$158.00
16	FRONT BUMPER FOG LAMP LH	1		\$516.00
17	FRONT BUMPER FOG LAMP RH	1		R \$516.00
18	FRONT FENDER LH	1		R \$938.00
19	FRONT FENDER "HYBRID" EMBLEM LH	1		R \$88.00
20	FRONT FENDER INNER SHIELD LH	1		cm \$186.00
21	FRONT FENDER QUARTER GLASS LH <i>with Mdy</i>	1		Dis \$224.00
22	FRONT RIM LH	1		R \$2,180.00
23	FRONT RIM RH	1		R \$2,180.00
24	FRONT ABSORBER LH	1		\$472.00
25	FRONT ABSORBER RH	1		\$472.00
26	FRONT LOWER ARM LH	1		\$899.00
27	FRONT LOWER ARM RH	1		\$899.00
28	FRONT KNUCKLE ARM LH	1		\$350.00
29	FRONT KNUCKLE ARM RH	1		\$350.00
30	FRONT WHEEL BEARING LH	1		\$158.00
31	FRONT WHEEL BEARING RH	1		\$158.00
32	FRONT STEERING RACK	1		\$2,115.00
33	FRONT FENDER RH	1		REPAIR
34	FRONT DOOR LH	1		REPAIR
35	FRONT DOOR RH	1		REPAIR

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 02/02/2023
 Vehicle No: SMK2598S
 Model: TOYOTA VOXY HYBRID 1.8V CVT
 Chassis: ZWR800352553-2018
 Reg.Year: 2019

Third Party Insurer: AIG
 Third Party Veh No: SLH7765X
 Date of Accident: 31/01/2023
 Estimator: TING AN
 Surveyor:

SUB TOTAL	\$21,549.00
LESS 25%	-\$5,387.25
PARTS TOTAL	\$16,161.75

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BONNET INSULATOR CLIPS	1		nn \$40.00	X
2	FRONT BUMPER CLIPS	1		nn \$50.00	—
3	FRONT GRILLE CLIPS	1		nn \$40.00	—
4	FRONT FENDER QUARTER GLASS SEALANT LH	1		nn \$80.00	3011-
5	FRONT TYRE LH	1		\$200.00	7
6	FRONT TYRE RH	1		Pr \$200.00	608m
S/N TOTAL				\$610.00	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

600d
\$1,400.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

1000d
\$1,400.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT FENDER QUARTER GLASS LH, FRONT FENDER QUARTER GLASS SEALANT LH & ETC.

\$150.00 401

LABOUR CHARGES TO REMOVE & REPLACE FRONT RIM LH & RH.

\$120.00 401

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER LH & RH, FRONT KNUCKLE ARM LH & RH, FRONT WHEEL BEARING LH & RH, FRONT LOWER ARM LH & RH, FRONT STEERING RACK & ETC.

\$500.00 ?

TO WHEEL ALIGNMENT & BALANCING.

\$100.00 701

Head office

6 Kung Chong Road Singapore 150143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 02/02/2023
Vehicle No: SMK2598S
Model: TOYOTA VOXY HYBRID 1.8V CVT
Chassis: ZWR800352553-2018
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLH7765X
Date of Accident: 31/01/2023
Estimator: TING AN
Surveyor:

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$100.00 7

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00 201

LABOUR TOTAL \$3,850.00

TING AN

TOTAL \$20,621.75

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011