



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

clear

marcushuc@11k.ko.on *Not Authorised*
7/12/23
whelpke beher 27
4 days

TP/DS *p/p # 4290-78*

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM <i>liability cheat</i> <i>India (Grab)</i> <i>III</i>			S1000020 / TPCLAIM		Mr Ong Wenjie 475D Upper Serangoon Crescent #11-557 Singapore 537475 Mobile: 98800223			
			Document No. 0					
			Document Date 25/01/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	NSP151R	AEXRKT E1	26/10/2020	SMV8735R	0	22325	69DS/SMV8735R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3501211400		2NR5458160	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SLF5481M ACC DATE:20/01/2023 TP INS: NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM				<i>am</i>		30.00
2	S	BP-SUBLET TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH CASING.				<i>3m</i>		68.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR BONNET				<i>17</i>		60.00
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME						198.00
5	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.					<i>72</i>	134.64
6	B	BP-LAB2 TO REPLACE/REPAIR FRONT ACCIDENT DAMAGE PARTS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS. <i>792</i>				<i>792</i>		3168.00
7	B	BP-RES2 TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS. <i>450</i>				<i>900</i>		2624.00
8	1	S81110-0DF01	HEADLAMP ASSY, RH	<i>holder era</i>	1.00	1547.20	<i>302</i>	1547.20
9	2	S81150-0DF01	HEADLAMP ASSY, LH	<i>an</i>	1.00	1547.20	<i>X</i>	1547.20
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

paid repair - supply materials ADD \$25

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mr Ong Wenjie				
		Document No. 0	475D Upper Serangoon Crescent #11-557 Singapore 537475				
		Document Date 25/01/2023	Mobile: 98800223				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP151R	AEXRKT E1	26/10/2020	SMV8735R	0	22325	69DS/SMV8735R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2B23F3501211400		2NR5458160	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
10	3	S53112-0D540 GRILLE, RADIATOR, LW <i>black grand</i>		1.00	323.80	<i>302</i>	323.80
11	4	S53113-0D020 GRILLE, RADIATOR, LW <i>cne</i>		1.00	109.30	<i>///</i>	109.30
12	5	S52119-0U932 COVER, FR BUMPER, L/ <i>de/turn</i>		1.00	592.80	<i>///</i>	592.80
13	6	S52161-0K040 PIECE, RR BUMPER <i>ner</i>		4.00	4.90	<i>///</i>	19.60
14	7	S52535-0D230 RETAINER, FR BUMPER <i>11</i>		1.00	120.70	<i>x</i>	120.70
15	8	S52536-0D230 RETAINER, FR BUMPER <i>11</i>		1.00	120.70	<i>x</i>	120.70
16	9	T90467-05170 CLIP <i>11</i>		2.00	3.00	<i>x</i>	6.00
17	0	T47749-33030 CLIP, PIN HOLD <i>11</i>		2.00	10.50	<i>x</i>	21.00
18	1	T53879-33030 RETAINER, FR FENDER <i>11</i>		2.00	14.60	<i>x</i>	29.20
19	2	S52021-0D140 REINFORCEMENT SUB-AS <i>R</i>		1.00	480.20	<i>x</i>	480.20
20	3	S53111-0D912 GRILLE, RADIATOR, OU <i>cne</i>		1.00	85.20	<i>/</i>	85.20
21	4	S53123-0D260 MOULDING, RADIATOR G <i>11</i>		1.00	47.30	<i>x</i>	47.30
22	5	S53124-0D380 MOULDING, RADIATOR G <i>11</i>		1.00	42.00	<i>x</i>	42.00
23	6	S53114-0D020 GRILLE, RADIATOR, IN <i>11</i>		1.00	288.00	<i>x</i>	288.00
24	7	T53119-12150 PROTECTOR, RADIATOR <i>11</i>		1.00	23.70	<i>x</i>	23.70
25	8	S53119-0D010 PROTECTOR, RADIATOR <i>11</i>		1.00	17.60	<i>x</i>	17.60
26	9	S90975-T2008 EMBLEM, SYMBOL <i>SEA</i>		1.00	70.10	<i>/</i>	70.10
27	0	S53301-0D280 HOOD SUB-ASSY <i>R</i>		1.00	1110.00	<i>x</i>	1110.00
28	1	S53208-0D901 SUPPORT SUB-ASSY, HO <i>R</i>		1.00	180.30	<i>x</i>	180.30
29	2	S53210-0D929 SUPPORT ASSY, RADIAT <i>R</i>		1.00	1173.80	<i>x</i>	1173.80
For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due	


Customer Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****ESTIMATE**

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Ong Wenjie 475D Upper Serangoon Crescent #11-557 Singapore 537475 Mobile: 98800223			
			Document No.					
			0					
			Document Date					
			25/01/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	NSP151R	AEXRKT E1	26/10/2020	SMV8735R	0	22325	69DS/SMV8735R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3501211400		2NR5458160	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
30	3	S53141-0D040 COVER, RADIATOR 			1.00	329.20	X	329.20
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____								
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd						14,567.54		
		Please acknowledge receipt of vehicle		Parts		8,284.90		
				Labour		6,214.64		
				Sublet		68.00		
				Lubrication/Fluid		0.00		
				Others		0.00		
				Total		14,567.54		
				GST 8.00%		1,165.40		
				Less		0.00		
				Amount Due		15,732.94		

Customer Copy