



**NATIONAL ASSESSMENT CENTRE SERVICES  
(LKK GROUP)**

**51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,  
Singapore 408933, TEL: 68410055 FAX: 68416315**

Your Ref : MT/1210240-001

Date: 06<sup>th</sup> Mar 2023

Our Ref : NS/INC23001201/Nqp3e2

**M/s Income Insurance Ltd**

75 Bras Basah Road

Income Centre

Singapore 189557

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHA 5276M  
INSURED VEHICLE: SLU 4976E  
ACCIDENT ON 21/01/2023**

Instruction was received to inspect the vehicle Reg. No. SHA 5276M. The inspection was conducted on 01/02/2023 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive, Singapore 508969.

The following vehicle information was recorded:

Registration Number	: SHA 5276M
Make/Model	: Hyundai I40 1.7 CRDI F/L AT ABS Airbag 4DR
Year of Registration	: 2015
Body Colour	: Blue
Chassis Number	: KMHLB41UMGU080538
Engine Capacity	: 1685 cc
Speedometer Reading	: Not Available

The vehicle sustained damages at the front o/s portion and o/s body. The Estimated repair cost of such vehicle is S\$6,350.00 (Sin Dollars: Six Thousand Three Hundred and Fifty only.) (Exclude check items S\$2,053.52Nett) (Details see photographs enclosed)



**NATIONAL ASSESSMENT CENTRE SERVICES  
(LKK GROUP)**

**51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,  
Singapore 408933, TEL: 68410055 FAX: 68416315**

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Book Value S\$ 19,517.00 (est)

Less: LTA Reimbursement Value (RV) (S\$ 17,009.00)

Nett Liability S\$ 2,508.00

S\$ 2,508.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) S\$ 6,350.00  
(Exclude check items S\$2,053.52Nett)

Nett Liability S\$ 6,350.00

(a) – (b) = (S\$ 3,842.00)

The amount of estimated saving of S\$3,842.00 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:

MUHD NAZRIL (NAZ)  
Technical Investigator  
LL.B. (Hons) London

K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.