

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA5618K

01.02.2023

MAKE REG. 15.12.2016

MODEL HYU- I40

CHIANG/ INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER			\$553.00	/CRA
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20	? X SVC
10	REAR BUMPER CLIPS		\$2.20	\$22.00	/NEC
1	REAR BUMPER REFLECTOR LH /RH		\$32.00	\$64.00	/
1	REAR BUMPER REINFORCEMENT			\$428.40	? X SVC
1	REAR BUMPER UNDER COVER			\$228.00	/CRA
1	BOOTLID			\$2,609.80	XR / DEF
1	BOOTLID LOWER GARNISH			\$227.90	/CRA
2	BOOTLID HINGES LH/RH		\$142.30	\$284.60	? X SVC
1	BOOTLID LAMP LH/RH		\$665.60	\$1,131.20	? X SVC
1	TAIL LAMP LH		\$697.80	\$1,395.60	? X SVC
1	BOOTLID MOULDING			\$85.00	/CRA
1	REAR FENDER LH			\$26.70	? X SVC
1	REAR FUEL LID LH			\$82.10	? X SVC
1	REAR END PANEL GARNISH			\$57.70	/CRA
1	REAR FENDER AIR DUCT LH			\$51.60	? X SVC
1	BOOTLID CDRI			\$52.40	/NEC
1	BOOTLID EMBLEM I40			\$67.90	/NEC
	SUB TOTAL		3,967.70	\$7,439.10	
	20.00%			\$1,487.82	
	DISCOUNTED TOTAL		3,174.16	\$5,951.28	
1	BOOTLID COFORT & TEL NO. STICKER			\$60.00	/NEC
1	BOOTLID ADVERTISEMENT			\$100.00	/NEC
2	REAR FENDER ADVERTISEMENT		\$100.00	\$200.00	/NEC
1	REAR BUMPER MAT			\$50.00	/NEC
1	REAR NUMBER PLATE			\$50.00	? X SVC
1	REVERSE SENSOR			\$135.70	/not working
			545.70	\$521.13	
	Labour Charge				
	Panel Beating			\$1,150.00	840
	Spray Painting Charge			\$1,000.00	750
	Remove/Refix Rear Upholstery			\$90.00	XNN
	Remove/refix reverse sensor			\$60.00	70
	Check lighting			\$60.00	? XNN
	Tuff Kote			\$100.00	50
	TOTAL LABOUR		1,670	\$2,460.00	
	ESTIMATE TOTAL		5,359.86	\$8,932.41	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: