



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:WINNIE		Ref: CC4/HSB23001218/Kpa3q2 Date: 03/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 363S	Veh. Inspected	GBF 4406G
Policy No.	P2478220	Coverage (\$)	0.00
Claim No.	S3M04IYB	Excess (\$)	0.00
Assign From		Assign Date	06/02/2023
2. Vehicle Particulars & Condition			
Make & Model	KIA K2500	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KNCSJX76LG7096921	Colour	WHITE
Odometer	160227 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	TRIANGLE	9 mm
L/H Front Tyre	195 R15X8	TRIANGLE	9 mm
R/H Rear Tyre	155 R12X8 (D)	CONDOR	8/8 mm
L/H Rear Tyre	155 R12X8 (D)	CONDOR	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/02/2023	Inspection Date	07/02/2023
Survey held at	FORZA AUTOHAUS PTE. LTD. 39 WOODLANDS CLOSE #01-34 MEGA@WOODLANDS SINGAPORE 737856		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	