

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

4/5 82100

TO : 90023571
MUHAMMAD FAHMI BIN ABDUL HAMID
BLK 860 TAMPINES AVENUE 5
02-651
SINGAPORE 520860
TEL : FAX :
PH : 90023571
ATTN :

ESTIMATE BILL

Number : EB00006199
Date : 03/02/2023
Case No : AD00013584
Vehicle No : SMJ8606T
Chassis : GK31338069
Year of Mfr : 2018
Policy No :
Model : HONDA FIT 1.3 GF
CVT

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT DOOR RH <i>3.2500</i>	1.0	848.30	20	678.64
2	FRONT DOOR HINGE TOP RH <i>u7</i>	1.0	42.00	20	33.60
3	FRONT DOOR HINGE BOTTOM RH <i>u7</i>	1.0	42.00	20	33.60
4	FRONT DOOR INNER LOCK RH <i>200</i>	1.0	<i>268.50</i>	20	
5	FRONT DOOR OUTER HANDLE RH <i>700</i>	1.0	351.50	20	281.20
6	FRONT DOOR OUTER KEY LOCK RH <i>u7</i>	1.0	98.50	20	78.80
7	FRONT FENDER RH <i>200/200</i>	1.0	<i>414</i> 509.40	20	407.52
8	FRONT DOOR GLASS REGULATOR WITH MOTOR RH <i>200/200</i>	1.0	<i>319</i> 416.50	20	333.20
9	FRONT DOOR TOP STICKER RH <i>u7</i>	1.0	41.00	20	32.80
10	FRONT DOOR MOULDING RH <i>u7</i>	1.0	59.10	20	47.28
List Price - Parts Sub Total					1,926.64
11	REAR DOOR RH - REPAIR <i>200</i>	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					1,926.64
12	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	<i>300</i> 800.00
13	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	<i>750</i> 800.00
14	ANTI-RUST COATING	1.0	100.00	0	<i>80</i> 100.00
Labour 1 Sub Total					1,700.00
SINGAPORE DOLLARS THREE THOUSAND NINE HUNDRED SIXTEEN AND CENTS SEVENTY-SEVEN ONLY					
Acknowledged by Repairer					
Signature:					
Date:					
Less Excess					0.00
SUBTOTAL					3,626.64
GST 8.00%					290.13
TOTAL					3,916.77

Date of accident : 30/01/2023 09:02 AM. Place : 38 MANDAI ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

1-1949.9
202
1559.52

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE