

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 19 Apr 2023

Preliminary Advice

Vehicle No	: SMQ9683B	Accident Date	: 02/02/2023
Make	: VOLKSWAGEN PASSAT B8	Policy No.	: SP2000682318
Assignment Date	: 06/02/2023	Excess	: S\$1,100.00
Date of Inspection	: 06/02/2023	Est. Duration of Repair	: 10
Inspection At	: VOLKSWAGEN GROUP SINGAPORE PTE LTD NO 17 TUAS AVE 9 SINGAPORE 639197		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,174.57	(Est \$20,984.74 + Supp \$189.83)
Revised Amount	:S\$	18,360.69	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	18,360.69	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	122,000.00
COE / PARF Rebate	:S\$	52,414.00
Salvage Value	:S\$	
Margin for Repair	:S\$	67,586.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please approve on Final figure amount.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour costs.