

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/4

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Ms.
LIM
IMM CHOO
4 BAYSHORE ROAD
SINGAPORE 469961

Document no.
Document date 04-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023003186/ 1
Job order date 03-02-2023
Service Advisor Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SMQ9683B	3G24JZC0	12-12-2019	VWVZZZ3CZKE057726	PASSAT Sed. HLBMT 132 D7F	50,183

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#6	200.00	216.00
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	360.00	388.80
9801B002	B&P LEAKED CHECK, VACUUM & REGAS				#6	280.00	302.40
9801B002	A/C GAS				#6	60.00	64.80
9801B001	TO ALIGN LED HEADLIGHT				#6	100.00	108.00
3G0823031C	Hood <i>buc</i>	1	pcs.	1,817.01	28.00%	1,308.25	1,412.91
3G0823301	Flap Hinge <i>3? 3bt</i>	1	pcs.	143.62	28.00%	103.41	111.68
	LH						
3G0823315C	Hinge Cover <i>3? X m</i>	1	pcs.	11.76	28.00%	8.47	9.15
	LH						
3G0823302	Flap Hinge <i>3bt</i>	1	pcs.	143.62	28.00%	103.41	111.68
	RH						
3G0823316C	Hinge Cover <i>3 X m</i>	1	pcs.	11.76	28.00%	8.47	9.15
	RH						
3G0823709	Decklid Weatherstrip <i>3 new</i>	1	pcs.	42.35	28.00%	30.49	32.93
	BONNET SEAL RH						
3G0823186B	Locking Catch <i>3bt</i>	1	pcs.	100.73	28.00%	72.53	78.33
	BONNET LATCH						
5G1823509D	Hood Latch <i>3? 6bt</i>	1	pcs.	232.18	28.00%	167.17	180.54
	BONNET LOCK						
5G2823531D	Cable Hood Latch <i>3? X m</i>	1	pcs.	51.28	28.00%	36.92	39.87
	LOCK CABLE						
WHT000425	Hexagon Socket Oval Head <i>3 new</i>	2	pcs.	2.90	28.00%	4.18	4.51
3G0863831A	Hood Silencer <i>3 de</i>	1	pcs.	282.10	28.00%	203.11	219.36
	BONNET INSULATOR						
3G2819404F 9B9	Cover For Plenum Chamber <i>3 X m</i>	1	pcs.	139.12	28.00%	100.17	108.18
	WIPER COWLING RH						
3G0807217K GRU	Cover For Bumper Primed <i>3 m</i>	1	pcs.	1,918.02	28.00%	1,380.97	1,491.45
3G0805903E 9B9	Spoiler Satin Black <i>3 X m</i>	1	pcs.	363.72	28.00%	261.88	282.83
3G0807109AB	Impact Beam <i>3bt</i>	1	pcs.	1,030.25	28.00%	741.78	801.12
	REINFORCEMENT						
3G0807651B	Cross Member <i>3bt</i>	1	pcs.	247.68	28.00%	178.33	192.60
N 90528204	Pop-Rivet <i>3 m</i>	2	pcs.	2.50	28.00%	3.60	3.89
3G0807251	Foam Insert <i>3 cm</i>	1	pcs.	142.13	28.00%	102.33	110.52
3G0807889	Guide Piece <i>3 cm</i>	1	pcs.	98.67	28.00%	71.04	76.72
	BUMPER CTR BRACKET <i>3 cm</i>						
3G0807178	Guide Piece <i>3 cm</i>	1	pcs.	56.51	28.00%	40.69	43.95
	BUMPER INNER BRACKET RH <i>3 cm</i>						
3G0807050	Guide Piece <i>3 m</i>	1	pcs.	61.54	28.00%	44.31	47.85
	BUMPER SIDE BRACKET RH <i>3 m</i>						
3G0807049	Guide Piece <i>3 X m</i>	1	pcs.	60.99	28.00%	43.91	47.42
	BUMPER SIDE BRACKET LH						
3G0998493	1 Set Sensor Brackets <i>3 m</i>	1	pcs.	53.33	28.00%	38.40	41.47
5Q0919275B GRU	Sensor Primed <i>3 m</i>	1	pcs.	194.63	28.00%	140.13	151.34



Quotation

Non binding - Preview

Page 2/4

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Ms.
LIM
IMM CHOO
4 BAYSHORE ROAD
SINGAPORE 469961

Document no.
Document date 04-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023003186/ 1
Job order date 03-02-2023
Service Advisor Dass Anthonidas Christopher

License plate	Model code	First registration	VIN	Model	Mileage		
SMQ9683B	3G24JZC0	12-12-2019	WVWZZZ3CZKE057726	PASSAT Sed. HLBMT 132 D7F	50,183		
Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5Q0919133 9B9	Seal Ring Satin Black	1	pcs.	1.53	28.00% #6	1.10	1.19
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	28.00% #6	60.94	65.82
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	28.00% #6	53.55	57.83
3G0971095GB	Harness For Bumper PARKING SENSOR WIRE HARNESS	1	pcs.	450.29	28.00% #6	324.21	350.15
3G0955104A	Pressure Cylinder With Je NOZZLE CYLINDER RH	1	pcs.	153.89	28.00% #6	110.80	119.66
3G0807938 GRU	Cap Primed NOZZLE COVER RH	1	pcs.	34.67	28.00% #6	24.96	26.96
7P6955964D	Schlauchleitung Schein We NOZZLE PIPE	1	pcs.	26.81	28.00% #6	19.30	20.84
3G0853651A BKZ	Radiator Grille Satin Bla	1	pcs.	687.72	28.00% #6	495.16	534.77
3G0853601B DPJ	Vw Sign Black/Bright Chro	1	pcs.	106.72	28.00% #6	76.84	82.99
3G0853671 9B9	Vent Grille With Trim Str BUMPER CTR LOWER GRILLE	1	pcs.	263.37	28.00% #6	189.63	204.80
3G0853245 2ZZ	Decorative Moulding Brigh BUMPER LOWER MLDG CHROM CTR	1	pcs.	259.65	28.00% #6	186.95	201.91
3G0853254 2ZZ	Decorative Moulding Brigh BUMPER LOWER MLDG CHROM RH	1	pcs.	118.97	28.00% #6	85.66	92.51
3G0854662 9B9	Cooling Air Grill Satin B RHS FOG LAMP GRILLE	1	pcs.	148.82	28.00% #6	107.15	115.72
3G0854322 9B9	Cover Strip Satin Black RHS FOG LAMP GRILLE LOWER TRIM	1	pcs.	81.69	28.00% #6	58.82	63.53
N 10666302	Tapping Screw Fill. Hd.	2	pcs.	1.32	28.00% #6	1.90	2.05
3G2941114A	Led Headlight	1	pcs.	3,135.30	28.00% #6	2,257.42	2,438.01
3G0941223	Adjustment Part H/LAMP ADJUSTMENT	1	pcs.	8.68	28.00% #6	6.25	6.75
3G0941120B	Trim Cover H/LAMP TOP CHROM	1	pcs.	44.15	28.00% #6	31.79	34.33
3G0998120	Repair Kit	1	pcs.	16.09	28.00% #6	11.58	12.51
3G0941120A	Gasket	1	pcs.	13.46	28.00% #6	9.69	10.47
7PP941572ABZ08	Power Module For Main Lig	1	pcs.	517.15	28.00% #6	372.35	402.14
3G0941329	Power Module For Led Head	1	pcs.	362.44	28.00% #6	260.96	281.84
4G0907697F	Power Module For Day Driv	1	pcs.	511.15	28.00% #6	368.03	397.47
3G0998477A	Led Lamp	1	pcs.	385.78	28.00% #6	277.76	299.98
N 91097201	Round Hd. Screw	2	pcs.	2.81	28.00% #6	4.05	4.37
1T0941111	Spacer	1	pcs.	33.83	28.00% #6	24.36	26.31
3C0973737	Flat Contact Housing With H/LAMP WIRE HOUSING	2	pcs.	21.99	28.00% #6	31.67	34.20
3G0941662L	Halogen Fog Lights With S	1	pcs.	401.82	28.00% #6	289.31	312.45
N 90959101	Speed Nut	1	pcs.	1.54	28.00% #6	1.11	1.20
N 90974701	Hexagon Socket Head Panel	1	pcs.	1.32	28.00% #6	0.95	1.03
3G0805588AC	Lock Carrier With Mountin	1	pcs.	1,566.47	28.00% #6	1,127.86	1,218.09
3G0805567A	Support For Lock Carrier	1	pcs.	40.84	28.00% #6	29.40	31.75
3G0805932	Cross Support H/LAMP TOP PANEL RH	1	pcs.	46.43	28.00% #6	33.43	36.10
3D0260749C	Seal Ring	1	pcs.	7.75	28.00% #6	5.58	6.03

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 3/4

Document no.
Document date 04-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023003186/ 1
Job order date 03-02-2023
Service Advisor Dass Anthonidas Christopher

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Ms.
LIM
IMM CHOO
4 BAYSHORE ROAD
SINGAPORE 469961

License plate SMQ9683B	Model code 3G24JZC0	First registration 12-12-2019	VIN VWVZZZ3CZKE057726	Model PASSAT Sed. HLBMT 132 D7F	Mileage 50,183			
Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST	
4D0260749B	Seal Ring	1	pcs.	8.23	28.00%	#6	5.93	6.40
G 055535M2	Oil For Refrigerant Compr	0.1	pcs.	394.77	28.00%	#6	28.42	30.69
	A/C OIL							
G 12E050A2	Coolant 1B	2	pcs.	25.14	28.00%	#6	36.20	39.10
3G0121284A	Air Duct	1	pcs.	32.38	28.00%	#6	23.31	25.17
	AIR GUIDE RH							
3Q0951221	Horn	1	pcs.	144.18	28.00%	#6	103.81	112.11
3G0951182A	Halter Fuer Signalhorn	1	pcs.	8.30	28.00%	#6	5.98	6.46
	HORN BRACKET							
4D0971992	Flat Connector Housing Wi	1	pcs.	14.83	28.00%	#6	10.68	11.53
	HORN WIRE HOUSING							
3G0821022B	Fender	1	pcs.	832.29	28.00%	#6	599.25	647.19
	RH							
3G0821142A	Bracket	1	pcs.	76.87	28.00%	#6	55.35	59.78
	RHS FENDER BRACKET							
3G0809471	Deformation Element	1	pcs.	28.19	28.00%	#6	20.30	21.92
	FENDER TOP BRACKET (FRT)							
3G0805970F	Wheelhouse Liner	1	pcs.	236.19	28.00%	#6	170.06	183.66
	FENDER LINER (UPPER)							
3G0805912T	Wheelhouse Liner	1	pcs.	179.80	28.00%	#6	129.46	139.82
	RHS FENDER LINER (LOWER)							
6N0809966A	Expanding Nut	8	pcs.	2.64	28.00%	#6	15.21	16.43
N 90974701	Hexagon Socket Head Panel	8	pcs.	1.32	28.00%	#6	7.60	8.21
3G0853992A GRU	Cover Primed	1	pcs.	64.15	28.00%	#6	46.19	49.89
	RHS FENDER LOWER COVER							
3G0853996D 3Q7	Cover Strip Chrome	1	pcs.	72.94	28.00%	#6	52.52	56.72
	RHS FENDER LOWER MLDG CHROM							
	ALLIANZ OD							
	DOA:02/02/2023							
	EXCESS:							
	SURVEY BY:							
	LABOUR	85	pcs.	560.00		#6	3,200.00	3,628.80
	SPRAY PAINT	85	pcs.	530.00		#6	3,180.00	3,434.40

Quotation valid till 10-02-2023

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#6	1,000.00	19,984.74	5,228.43	8%	1,678.78	5,228.43	20,984.74	22,663.52
Total	1,000.00	19,984.74	5,228.43		1,678.78	5,228.43	20,984.74	22,663.52



Quotation

Non binding - Preview

Company
ALLIANZ
INSURANCE SINGAPORE PTE. LTD.
79 ROBINSON ROAD
#09-01
SINGAPORE 068897

Customer Details:
Ms.
LIM
IMM CHOO
4 BAYSHORE ROAD
SINGAPORE 469961

Page 4/4
Document no.
Document date 04-02-2023
Customer no. 5211052769
Customer GST-ID 201903913C
Dealer 30001
Job order number 2023003186/ 1
Job order date 03-02-2023
Service Advisor Dass Anthonidas
Christopher

License plate SMQ9683B	Model code 3G24JZC0	First registration 12-12-2019	VIN VWVZZZ3CZKE057726	Model PASSAT Sed. HLBMT 132 D7F	Mileage 50,183
---------------------------	------------------------	----------------------------------	--------------------------	------------------------------------	-------------------

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rahul
Hf 9001w 68
10 days
P/P
06/02/23 @ 1450
EXCESS: TDA
Revert
Resy before paint

Supplementary or Omitted List



VEHICLE NUMBER: **SMQ9683B**

MODEL **PASSET**

CLAIMS DETAILS

	LABOUR DESCRIPTION	AMOUNT		
Total				\$0.00

No.	Item No.	Description	Qty	Unit Price	Discount	Amount
	5G0823535B	LOCK CABLE INNER <i>cul</i>	1	107.86		107.86 <i>77.66</i>
	3G0864236L	RHS FENDER ELEMENT <i>de</i>	1	81.97		81.97 <i>59.02</i>

\$ 189.83

Total Labour & Parts

\$189.83

SURVEY By

RASUL