



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23001230/Kqy3m4 Date: 14/02/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YM 9569C	Veh. Inspected	SKL 3146A
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS23/0299	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	06/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	MR053REE104166071	Colour	METALLIC SILVER
	Odometer	260951 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	GRENLANDER	9 mm
	L/H Front Tyre	195/65 R15	GRENLANDER	9 mm
	R/H Rear Tyre	195/65 R15	GRENLANDER	9 mm
	L/H Rear Tyre	195/65 R15	GRENLANDER	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/01/2023	Inspection Date	06/02/2023
	Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		
5a. Remarks				
	A)REGISTRATION DATE: 28 OCT 2013 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	