

(08/11/13) wef

ASS. REC. BY: Paul

REF:

C/EH1 23001233/Rgy3

127A

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMP 1166K

at Workshop m/s

Premium

of

24, Piroi skool

Insured:

EHI

Policy No.

Claims No.

Sum Insured:

Excess:

1000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

98K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMP 1166K

Yr Regn:

2019 July

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 SEDAN / 0 TFSI ST c.c. 999

Colour:

RED

A/C:

Insured / Std / NI / NA

Sp. Reading

43451

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAN 222 8V7K1025599

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/402R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

23/01/23

D.O.I.

08/02/23

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 62K

Rasul finalised final fig \$28454.90, 8 days. (Red \$18270.10, 39%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

8

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS SI

) Photos

) Others

Report Format :

MER-OD

Lump Sum / I.B.I: (\$

28454.90

)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0140/2023/EQ
DATE : 6-Feb-23
WIP : 61570

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/2/2023

ERGO Insurance Pte Ltd

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR WONG SIEW JOO
ADDRESS : 1 LENGKONG EMPAT
#11-01
SINGAPORE 417609
TELEPHONE : HP +65 98443438
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : DMPG22009893
VEHICLE NO : **SMP 1166 K**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 26/7/2019
ENGINE NO : CHZ C27818
CHASSIS NO : WAUZZZ8V7K1025599
MILEAGE : -
DATE IN : 2-Feb-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Jan-23
PLACE OF ACCIDENT : JALAN SENANG

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 1166 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 ✓	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. RENEW WHERE NECESSARY.	S/N \$ 1,400.00 ?	
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00 ✓	
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,000.00 @ 700 x 5 = 3500 ✓ 2450	
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, LHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT, BONNET, HINGES AND RHS FRONT DOOR.	\$ 5,000.00 @ 700 x 5 = 3500 + 1500 ✓ 3600	
TOTAL LABOUR CHARGES		: \$ 14,390.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 1166 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RENEW BOTH FRONT RIMS. TO CARRY OUT WHEEL ALIGNMENT.	S/N \$ 320.00	/
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 14,902.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER CLOSING ELEMENT - RH <i>MS ✓</i>	1	\$ 337.00	
2	FRONT BUMPER GUIDE SECTION - RH <i>cu ✓</i>	1	\$ 46.00	
3	FRONT BUMPER FOAM FILLER PIECE <i>X</i>	1	\$ 224.00	
4	FRONT BUMPER REINFORCEMENT BEAM <i>lt ✓</i>	1	\$ 974.00	
5	FRONT BUMPER REINFORCEMENT BEAM COVER <i>X</i>	1	\$ 144.00	
6	AIR CONDITIONER STICKER <i>X</i>	1	\$ 9.00	
7	CAUTION SIGN STICKER <i>X</i>	1	\$ 17.00	
8	HORN LOW TONE - RH <i>cu ✓</i>	1	\$ 225.00	
9	FRONT FENDER - RH <i>bu ✓</i>	1	\$ 1,012.00	
10	FRONT FENDER RIVET <i>n ✓</i>	5	\$ 20.00	
11	FRONT FENDER ATTACHMENT PARTS <i>?</i>	1	\$ 80.00	
12	FRONT FENDER BRACKET - RH CENTER <i>lt ✓</i>	1	\$ 57.00	
13	FRONT FENDER BRACE <i>?</i>	1	\$ 114.00	
14	FRONT FENDER BRACKET - RH REAR <i>bu ✓</i>	1	\$ 38.00	
15	FRONT FENDER INSULATION - RH <i>X</i>	1	\$ 51.00	
16	FRONT FENDER CLOSING ELEMENT - RH <i>?</i>	1	\$ 39.00	
17	FRONT WHEEL HOUSING LINER - RH <i>de ✓</i>	1	\$ 198.00	
18	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>n ✓</i>	1	\$ 99.00	
19	BONNET <i>bu ✓</i>	1	\$ 3,412.00	
20	BONNET ATTACHMENT PARTS <i>X</i>	1	\$ 182.00	
SUB TOTAL SPARE PARTS		:	\$ 7,278.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET HINGE - LH / RH ?	2	\$	146.00
22	BONNET EDGE PROTECTION r/	1	\$	33.00
23	BONNET STRIKER - RH ?	1	\$	130.00
24	BONNET LOCK ?	1	\$	241.00
25	BONNET CATCH HOOK ?	1	\$	106.00
26	BONNET CATCH HOOK ?	1	\$	75.00
27	BONNET BOWDEN CABLE - CENTER ?	1	\$	67.00
28	BONNET RELEASE CABLE COVER ?	1	\$	12.00
29	BONNET LOCK CABLE ?	1	\$	87.00
30	BONNET ENGINE SOUND ABSORBER X	1	\$	260.00
31	FRONT PLENUM CHAMBER COVER ?	1	\$	211.00
32	BONNET SIDE SEAL - RH ?	1	\$	51.00
33	HEADLIGHT - RH lo/	1		TBC
34	HEADLIGHT POWER MODULE - RH short X	1	\$	876.00
35	HEADLIGHT HEAT SINK - RH ?	1	\$	868.00
36	HEADLIGHT CONTROL UNIT short/	1	\$	643.00
37	HEADLIGHT HOSE - RH ?	1	\$	48.00
38	LIFT CYLINDER - RH cin/	1	\$	165.00
39	LIFT CYLINDER HOSE at/	1	\$	81.00
40	LOCK CARRIER ?	1	\$	854.00
SUB TOTAL SPARE PARTS		:	\$	4,954.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K
DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	A/C CONDENSER ?	1	\$ 586.00	
42	A/C CONDENSER REFRIGERANT LINE ?	1	\$ 627.00	
43	A/C CONDENSER REFRIGERANT LINE ?	1	\$ 503.00	
44	A/C CONDENSER REFRIGERANT LINE ?	1	\$ 574.00	
45	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 22.00	
46	ADDITIONAL RADIATOR ?	1	\$ 967.00	
47	RADIATOR BRACKET - LH / RH UPPER ?	2	\$ 92.00	
48	RADIATOR BUSH - LH / RH LOWER ?	2	\$ 22.00	
49	RADIATOR ?	1	\$ 1,099.00	
50	READY-MIX COOLANT ?	6	\$ 326.00	
51	RADIATOR AIR GUIDE - RH ?	1	\$ 31.00	
52	RADIATOR AIR GUIDE SEAL - RH OUTER ?	1	\$ 10.00	
53	RADIATOR AIR GUIDE - UPPER CENTRE ?	1	\$ 20.00	
54	AIR INLET COVER ?	1	\$ 31.00	
55	RADIATOR AIR GUIDE ?	1	\$ 60.00	
56	RADIATOR AIR GUIDE ?	1	\$ 21.00	
57	WATER DRAINAGE HOSE ?	1	\$ 38.00	
58	RADIATOR AIR GUIDE ?	1	\$ 71.00	
59	AIR FILTER ? X	1	\$ 356.00	
60	AIR FILTER INTAKE MANIFOLD X	1	\$ 793.00	
SUB TOTAL SPARE PARTS		:	\$ 6,249.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 1166 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT THROTTLE VALVE CONTROL ELEMENT X	1	\$ 812.00	
62	CHARGE AIR COOLER X	1	\$ 872.00	
63	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - RH X	1	\$ 366.00	
64	FRONT WINDOW GUIDE CHROME TRIM STRIP - RH X	1	\$ 304.00	
65	FRONT NOISE INSULATION ?	1	\$ 437.00	
66	FRONT FENDER END PLATE - RH repair	1	\$ 101.00	
67	FRONT ALUMINIUM RIM - LH / RH cut	2	\$ 2,760.00	LH - Subject to report
68	FRONT ALUMINIUM RIN RUBBER VALVE - LH / RH	2	\$ 8.00	LH subject to report
69	FRONT NUMBER PLATE ?	S/N	\$ 150.00	
70	FRONT BUMPER ASSY turn	S/N	TBC	
71	SUNDRIES ?		\$ 500.00	
TOTAL SPARE PARTS			\$ 24,791.00	
TOTAL LABOUR CHARGES			\$ 14,902.00	
GRAND TOTAL			\$ 39,693.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

*Pass - Hg 90010688
68/02/23 @ 1030
8 days
EXCESS: TBA
Reveal
Reem before paint*

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	127A
Vehicle Details	
Vehicle No.:	SMP1166K
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Feb 2023
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED & NAV)
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	CHZC27818
Chassis No.:	WAUZZZ8V7K1025599
Maximum Power Output:	85.0kW (113 bhp)
Open Market Value:	\$23,355.00
Original Registration Date:	26 Jul 2019
First Registration Date:	26 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$24,697.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jul 2029
PARF Rebate Amount:	\$18,522.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jul 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,667.00
COE Rebate Amount:	\$17,233.00
Total Rebate Amount:	\$35,755.00

The information contained herein is correct as at 08 Feb 2023

Audi A3 Sedan 1.0A TFSI S-tronic

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$98,800****Depreciation** ⓘ

\$13,560 /yr

[View models with similar depre](#)**Reg Date**

18-Jul-2019

(6yrs 5mths 9days COE left)

Mileage

84,000 km (23.6k /yr)

Manufactured ⓘ

2019

Road Tax ⓘ

\$392 /yr

Transmission

Auto

Dereg Value ⓘ\$34,364 as of today ([change](#))**OMV** ⓘ

\$22,083

COE ⓘ

\$26,667

ARF ⓘ

\$22,917

Engine Cap

999 cc

Power

85.0 kW (113 bhp)

Curb Weight ⓘ

1,280 kg

No. of Owners ⓘ

1

Type of Vehicle[Luxury Sedan](#)