

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

HSBC LIFE (SINGAPORE) PTE LTD

10 MARINA BOULEVARD

#48-01 MARINA BAY FINANCIAL CENTRE

TOWER 2

SINGAPORE 018983 ATTN: HO WINNIE

PROFESSIONAL SERVICE FEE

Vehicle No. GBG 1011B

Insured Veh. SHC 2331X

Claim No. S3M04IUN

Policy No. VFX/P2419138

Accident Date 01/02/2023

Inspection Date 21/02/2023

IN V NO. AC2303300	INV No.	AC2303300
--------------------	---------	-----------

INV Date 25/05/2023

Reference CS3/HSB23001235/Wnp3e2

Code HSB

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 21.02.2023)	
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 22.02.2023)	
Subtotal	100.00
GST (8%)	8.00
Grand Total	108.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM