

ASS. REC. BY:

REF:

TY / 23001236/Kny3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TPRES/ODRES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

750

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

\$57k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

00

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SLE 36225

Yr Regn: _____

07, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Toy AIAJ

c.c

1598

Colour: _____

M. D. Gray

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

10198

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

MR053REH104554966

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Davant

Front

Rear

R/Bal. _____

5

mm

R/Bal. _____

4

mm

L/Bal. _____

5

mm

L/Bal. _____

4

mm

D.O.A. _____

22/1/23

D.O.I. _____

6/2/2023

Survey held at _____

Des. of Damages (Frt) Rear / O/S / N/S / U/C / Rooftop or

& Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/1/23 11:00 AM @ 7650/1 Central (Red. # 6151.82, 4470)

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair: _____

8

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee: _____

Transportation: _____

S - RS. \$

Fees

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	775H
Vehicle Details	
Vehicle No.:	SLE3622S
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Feb 2023
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRX587166
Chassis No.:	MR053REH104554966
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,982.00
Original Registration Date:	19 Jul 2016
First Registration Date:	19 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$17,982.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jul 2026
PARF Rebate Amount:	\$11,688.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$16,280.00
Total Rebate Amount:	\$27,968.00

The information contained herein is correct as at 01 Feb 2023

OK

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg; samuelxie@cdge.com.sg

INSURER:

India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: D20MFL0000326_02
Vehicle Reg. No.: **SLE3622S**
Driver Age/Info: NO
TP Injury Involved? NO
Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD

Ref. No:
Date of Loss: 22/01/2023
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES

Make/Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC
CVT (A)
Vehicle Colour: GREY
Engine No: 1ZRX587166
Odometer: 0 KM

Vehicle Reg. Date: 19/07/2016
Chassis No: MR053REH104554966

Paint Type:
List Item Discount: 25.00 %
Total Loss? **NO**
Est. Duration of Repair (day) 8 ✓

Not Notified
11 Pm @ 7650h
Repair After Rain
Ex @ 750h

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

COST OF CLAIMS		Amount
Parts		9,325.27
Miscellaneous Items		161.00
Labour		3,530.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		13,016.27
+ GST 8.00% (S\$)		1,041.30
Nett Amount (S\$)		14,057.57

This claim is handled by: OI SUN PIN

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Feb 2023)
Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLE3622S)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	25.00	0.00	CM *639.80 FL	✓
2	1		*FRONT CHROME GRILLE 643.10	25.00	0.00	CM *770.80 FL	✓
3	1		*FRONT LOWER GRILLE	25.00	0.00	CM *94.40 FL	X
4	1		*LH HEADLAMP	25.00	0.00	CM *885.80 FL	✓
5	1		*RH HEADLAMP	25.00	0.00	CM *885.80 FL	✓
6	1		*FRONT BUMPER LH RETAIER	25.00	0.00	Dis *102.60 FL	✓
7	1		*FRONT BUMPER RH RETAINER	25.00	0.00	Dis *102.60 FL	✓
8	1		*FRONT SUPPORT PANEL	25.00	0.00	R *1,364.00 FL	X
9	1		*FRONT BONNET	25.00	0.00	Ry *107.60 FL	✓
10	1		*FRONT BONNET LOCK	25.00	0.00	R *162.20 FL	X
11	1		*REAR BOORLID 947.10	25.00	0.00	Ry *947.10 FL	✓
12	1		*REAR BOOTLID LH HINGE	25.00	0.00	R *83.90 FL	X
13	1		*REAR BOOTLID RH HINGE	25.00	0.00	R *83.90 FL	X
14	1		*REAR BOOTLID INSULATOR	25.00	0.00	Rn *437.30 FL	X
15	1		*REAR BOOT WHEATHERSTRIP	25.00	0.00	Sn *211.10 FL	X
16	1		*REAR BOOTLID LOCK 409.10	25.00	0.00	Dis *480.20 FL	✓
17	1		*REAR BOOTLID CHROME MOULDING	25.00	0.00	Sn *292.50 FL	X
18	1		*REAR BOOTLID TOYOTA EMBLEM	25.00	0.00	Sn *79.70 FL	✓
19	1		*REAR BOOT LID COROLLA EMBLEM	25.00	0.00	Sn *81.50 FL	✓
20	1		*REAR VOOTLID ALTIS EMBLEM	25.00	0.00	Sn *91.60 FL	✓
21	1		*REAR BOOTLID LH LAMP	25.00	0.00	CRS *244.60 FL	✓
22	1		*REAR BOOTLID RH LAMP	25.00	0.00	CM *244.60 FL	✓
23	1		*LH TAILLAMP 394.50	25.00	0.00	CM *456.10 FL	✓
24	1		*RH TAILLAMP 394.50	25.00	0.00	CM *456.10 FL	✓
25	1		*LH TAILLAMP CLIP	25.00	0.00	Sn *6.50 FL	✓
26	1		*RH TAILLAMP CLIP	25.00	0.00	Sn *6.50 FL	✓
27	1		*LH TAILLAMP BRACKET	25.00	0.00	Sn *72.80 FL	X
28	1		*RH TAILLAMP BRACKET	25.00	0.00	Sn *72.80 FL	X
29	1		*REAR BUMPER 669.10	25.00	0.00	Ry *669.10 FL	✓
30	1		*REAR BUMPER LH REFLECTOR	25.00	0.00	Sn *72.70 FL	X
31	1		*REAR BUMPER RH REFLECTOR	25.00	0.00	Sn *72.70 FL	X
32	1		*REAR BUMPER LH RETAINER	25.00	0.00	Dis *131.80 FL	✓
33	1		*REAR BUMPER RH RETAINER	25.00	0.00	Dis *131.80 FL	✓
34	1		*REAR LH FENDER INNER TRIM	25.00	0.00	Sn *396.40 FL	X
35	1		*REAR RH FENDER INNER TRIM	25.00	0.00	Sn *396.40 FL	X
36	1		*REAR END PANEL 808	25.00	0.00	Ry *808.00 FL	✓
37	1		*REAR END PANEL GARNISH 290.40	25.00	0.00	Dis *290.40 FL	✓

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	12,433.70
- List Item Discount on L Items (\$)	3,108.43
Total Parts (\$)	9,325.27

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT BUMPER CLIPS
2	1	REAR BOOTLID CLIPS
3	1	RER BUMPER CLIPS
4	1	OD/TP Case (Insurer)

Mr 50.00 ✓
Mr 50.00 ✓
Mr 50.00 ✓
11.00 ✓

Sub Total (S\$) 161.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	To knock & straighten on accident area, to remove & refit Front damage parts.
2	To putty & respray on Front damage parts.
3	To knock & straighten on accident area, to remove & refit Rear damage parts.
4	To putty & respray on Rear damage parts.
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.
6	To check wiring, focus headlamp & install reverse sensor.

400l
New 600.00
New 600.00 *400l*
New *800l* 1,200.00
New *800l* 1,000.00
New 80.00 ✓
New 50.00 ✓

Gross Labour Cost (S\$) 3,530.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO.: **SLE3622S**
MAKE: TOYOTA
MODEL: COROLLA
YEAR OF MAKE: 2016
CHASSIS NO.: MR053REH104554966

0

PAGE 1

COST / LIST

S/N	Parts Description	PART NUMBER	Qty	Remarks	
				COST	LIST
1	SPARE TYRE TOP BOARD <i>292</i>		1	<i>CM</i>	\$ 390.40 ✓
2	REAR BUMPER REINFORCEMENT <i>408.20</i>		1	<i>B1</i>	\$ 480.20 ✓
3	REAR BUMPER LOWER BRACKET-RH		1	<i>CM</i>	\$ 131.80 ✓
4	FRT NO.PLATE		1	<i>B1</i>	\$ 45.00 ✓
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					