

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg;samueltie@cdge.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D20MFL0000326_02	Date of Loss:	22/01/2023
Vehicle Reg. No.:	SLE3622S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD		

Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Vehicle Reg. Date:	19/07/2016
Vehicle Colour:	GREY	Chassis No:	MR053REH104554966
Engine No:	1ZRX587166		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	8 ✓		

Not Whairu
1/100 @
Repair After Rain

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

COST OF CLAIMS		Amount
Parts		9,325.27
Miscellaneous Items		161.00
Labour		3,530.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		13,016.27
+ GST 8.00% (S\$)		1,041.30
Nett Amount (S\$)		14,057.57

This claim is handled by: OI SUN PIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

PAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Feb 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE3622S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

QTY	Part No.	Particulars	%Disc	%Depr	Amount	
1		*FRONT BUMPER	25.00	0.00	CM *639.80 FL	✓
1		*FRONT CHROME GRILLE	25.00	0.00	CM *770.80 FL	✓
1		*FRONT LOWER GRILLE	25.00	0.00	LM *94.40 FL	X
1		*LH HEADLAMP	my CM 25.00	0.00	*885.80 FL	✓
1		*RH HEADLAMP	25.00	0.00	*885.80 FL	✓
1		*FRONT BUMPER LH RETAIER	25.00	0.00	DIY *102.60 FL	✓
1		*FRONT BUMPER RH RETAINER	25.00	0.00	DIY *102.60 FL	✓
1		*FRONT SUPPORT PANEL	25.00	0.00	R *1,364.00 FL	X
1		*FRONT BONNET	25.00	0.00	R *107.60 FL	✓
1		*FRONT BONNET LOCK	25.00	0.00	R *162.20 FL	X
1		*REAR BOORLID	25.00	0.00	R *947.10 FL	✓
1		*REAR BOOTLID LH HINGE	25.00	0.00	R *83.90 FL	X
1		*REAR BOOTLID RH HINGE	25.00	0.00	R *83.90 FL	X
1		*REAR BOOTLID INSULATOR	25.00	0.00	R *437.30 FL	X
1		*REAR BOOT WHEATHERSTRIP	25.00	0.00	*211.10 FL	?
1		*REAR BOOTLID LOCK	25.00	0.00	DIY *480.20 FL	✓
1		*REAR BOOTLID CHROME MOULDING	25.00	0.00	*292.50 FL	?
1		*REAR BOOTLID TOYOTA EMBLEM	25.00	0.00	LM *79.70 FL	✓
1		*REAR BOOT LID COROLLA EMBLEM	25.00	0.00	LM *81.50 FL	✓
1		*REAR VOOTLID ALTIS EMBLEM	25.00	0.00	LM *91.60 FL	✓
1		*REAR BOOTLID LH LAMP	25.00	0.00	CRS *244.60 FL	✓
1		*REAR BOOTLID RH LAMP	25.00	0.00	CM *244.60 FL	✓
		*LH TAILLAMP	25.00	0.00	CM *456.10 FL	✓
		*RH TAILLAMP	25.00	0.00	CM *456.10 FL	✓
		*LH TAILLAMP CLIP	25.00	0.00	LM *6.50 FL	✓
		*RH TAILLAMP CLIP	25.00	0.00	LM *6.50 FL	✓
		*LH TAILLAMP BRACKET	25.00	0.00	*72.80 FL	?
		*RH TAILLAMP BRACKET	25.00	0.00	*72.80 FL	?
		*REAR BUMPER	25.00	0.00	R *669.10 FL	✓
		*REAR BUMPER LH REFLECTOR	25.00	0.00	LM *72.70 FL	X
		*REAR BUMPER RH REFLECTOR	25.00	0.00	LM *72.70 FL	X
		*REAR BUMPER LH RETAINER	25.00	0.00	DIY *131.80 FL	✓
		*REAR BUMPER RH RETAINER	25.00	0.00	DIY *131.80 FL	✓
		*REAR LH FENDER INNER TRIM	25.00	0.00	LM *396.40 FL	X
		*REAR RH FENDER INNER TRIM	25.00	0.00	LM *396.40 FL	X
		*REAR END PANEL	25.00	0.00	R *808.00 FL	✓
		*REAR END PANEL GARNISH	25.00	0.00	DIY *290.40 FL	✓

e part. L=ListItemDisc.

Sub Total (\$)	12,433.70
- List Item Discount on L Items (\$)	3,108.43
Total Parts (\$)	9,325.27

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER CLIPS	50.00 ✓
2	1	REAR BOOTLID CLIPS	50.00 ✓
3	1	RER BUMPER CLIPS	50.00 ✓
4	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			161.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To knock & straighten on accident area, to remove & refit Front damage parts.	New	600.00 400 ✓
2	To putty & respray on Front damage parts.	New	600.00 400 ✓
3	To knock & straighten on accident area, to remove & refit Rear damage parts.	New	1,200.00 800 ✓
4	To putty & respray on Rear damage parts.	New	1,000.00 800 ✓
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	New	80.00 ✓
6	To check wiring, focus headlamp & install reverse sensor.	New	50.00 ✓
Gross Labour Cost (S\$)			3,530.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: