

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC23001242/Rvy3	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	06/02/2023	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YN 5241T	Veh. Inspected		SNG 1169M	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VC05/026926	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		06/02/2023	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.						
	Accident Date	01/02/2023	Inspection Date)	07/02/2023	
	Survey held at	SK GARAGE				
		NO. 5 SOON LEE STREET #01-34 SINGAPORE 627607				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					