



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/LPC22011254/Tqy3-1

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: ~~CS3/LPC22011254/Tqy3-1~~

Date: ~~09/11/2022~~ 04/02/2023

Code: LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBJ 1328Y	Veh. Inspected	GBH 1591M
Policy No.		Coverage (\$)	0.00
Claim No.	22/22/22/VC05/026524	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	09/11/2022 04/02/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/11/2022	Inspection Date	
Survey held at	37 Loyang Way Singapore 508734		
Repairer	MICHELIN ENGINEERING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--