

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: HL Assurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	23/HL/OD-057 (02)
Policy No:	MP306018	Date of Loss:	04/02/2023
Vehicle Reg. No.:	SLF8414M	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HENG CHIN GUAN	Contact No:	+6597367219
Driver:	HENG KAI MIN DAMIAN		
Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	13/09/2016
Vehicle Colour:	GREY		
Engine No:	2ZR1831929	Chassis No:	JTDGG20W80J005080
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Remarks:	VEHICLE IN.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	7,162.10
Miscellaneous Items	305.00
Labour	2,210.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	9,677.10
+ GST 8.00% (\$\$)	774.17
Nett Amount (\$\$)	10,451.27

This claim is handled by: CHIA PEI YING

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Feb 2023)
Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SLF8414M/07/02/2023 13:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>Deep cut</i> ✓	0.00	0.00	*290.00 F
2	10		*FRT BUMPER CLIP <i>ner</i> ✓	0.00	0.00	*20.00 F
3	1		*FRT BUMPER UNDER COVER	0.00	0.00	*95.00 F
4	1		*FRT RH SHOCK ABSORBER <i>Sent</i> ✓	0.00	0.00	*235.00 F
5	1		*FRT RH SHOCK ABSORBER MOUNTING ?	0.00	0.00	*105.00 F
6	1		*FRT RH LOWER ARM <i>Sent</i> ✓	0.00	0.00	*195.00 F
7	1		*RFT RH LOWER ARM BALL JOINT <i>Sent</i> ✓	0.00	0.00	*95.00 F
8	1		*FRT RH KNUCKLE ARM <i>Sent</i> ✓	0.00	0.00	*255.00 F
9	1		*FRT RH KNUCKLE BEARING <i>ner</i> ✓	0.00	0.00	*90.00 F
10	1		*FRT RH DRIVE SHAFT ?	0.00	0.00	*750.00 F
11	1		*ANTI ROLL BAR ?	0.00	0.00	*235.00 F
12	1		*ANTI ROLL BAR LINK RH ?	0.00	0.00	*95.00 F
13	1		*STEERING RACK ASSY ?	0.00	0.00	*850.00 F
14	1		*STEERING CROSSMEMBER ?	0.00	0.00	*950.00 F
15	1		*CENTER CROSSMEMBER ?	0.00	0.00	*245.00 F
16	1		*FRT ENGINE MOUNTING ?	0.00	0.00	*165.00 F
17	1		*REAR ENGINE MOUNTING ?	0.00	0.00	*135.00 F
18	1		*FRT ENGINE UNDER COVER ?	0.00	0.00	*95.00 F
19	8		*ENGINE UNDER COVER CLIP <i>ner</i> ✓	0.00	0.00	*16.00 F
20	1		*FRT RH FENDER INNER COWLING <i>ner</i> ✓	0.00	0.00	*115.00 F
21	10		*INNER COWLING CLIP <i>ner</i> ✓	0.00	0.00	*20.00 F
22	1		*REAR RH SHOCK ABSORBER ?	0.00	0.00	*130.00 F
23	1		*REAR RH WHEEL HUB ?	0.00	0.00	*380.00 F
24	1		*REAR AXLE ?	0.00	0.00	*950.00 F
25	2		*RH SPORTS RIM <i>wages</i> ✓	0.00	0.00	*- F
			SAMPLE			

F=Franchise part.

Sub Total (\$\$)	6,511.00
+ Margin on L,N Items 10.00% (\$\$)	651.10
Total Parts (\$\$)	7,162.10

SME Motor Pte Ltd/SLF8414M/07/02/2023 13:09. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRT RH TYRE ?	280.00
2	1	RADIATOR COOLANT 11 X	25.00
Sub Total (\$\$)			305.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New 20	30.00
2	REMOVE & REFIX AIRCON AND GAS	New 11 X	100.00
3	REMOVE & REFIX FRT UNDERCARRIAGE (WITH CROSSMEMBER & RACK)	New ✓	350.00
4	REMOVE & REFIX REAR UNDERCARRIAGE (WITH AXLE)	New ?	350.00
5	4 WHEEL ALIGNMENT	New 60	80.00
6	LABOUR CHARGE	New 300	600.00
7	SPRAY PAINTING	New 400	700.00
Gross Labour Cost (\$\$)			2,210.00

SME Motor Pte Ltd/SLF8414M/07/02/2023 13:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >