



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HL ASSURANCE PTE LTD 11 KEPPEL ROAD #11-01 ABI PLAZASINGAPORE 089057			Ref: CS/HLA23001283/Uqy3 Date: 07/02/2023 Code: HLA	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SLF 8414M	
	Policy No. MP306018	Coverage (\$)	0.00	
	Claim No. MPC03977/RL	Excess (\$)	0.00	
	Assign From ROMEO JONNALYN ALAAN	Assign Date	07/02/2023	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date 04/02/2023	Inspection Date	08/02/2023	
	Survey held at SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			