C12 REF: ASS. REC. BY: Kenneth ASSIGNMENT SNB 94337 Yr Regn: 09, 21 Veh No: From: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost: Truck / Trailer or OD / TP / WS / TP RES / OD RES / EVA / INV / MY Make: To Inspect Vehicle No: M. Black Insured / Std / NI / NA Colour at Workshop m/s 105246 T/Radio: Insured / Std / N1 / NA Sp.Reading Eng/No: Insured: ZWR C/No: Policy No. Gen. Cond: Bood / Fair / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Excess: Sum Insured: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: NII / S/RIM / STE A/RIM or Make of Veh: 195/65R15 Tyre Stze: (Policy Condition) Remark: The veh had commenced its O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. TOYO / YOKO or Bal. or Market Value: 8/82K Front IDAC Accident Roort: Consistent?: Yes or No Consistent?: Yes or No GIA / PR Seen: L/Bal. Est. Repairs: Res.: Yes or No D.O.I. Lum Sum: 3 Val.: Yes or No Survey held at CA / REV / REP. / 24 HRS Des. of Damages : Frt | Rear | O/S | N/S | U/C | Rooftop or Vehicle: IN / OUT Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction Ŕs Date/Time, File Pass to? Prell. Report Days Of Repair: Final Report Resurvey No. of Trip: Survey Fee: Cuta/Time, File Return to? Transportation Add Fee: Site Insp (\$ Interview (\$ Report Format: Tech Invs (\$ 1 Others Lump Sum / I.B.I: (S Weekend (\$

17.7A.



MY CAR CONSULTANT PTE LTD

Not Maharike URy & Reany Afa Pains Palage

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 \$737896 HP: 98888885

Reg no.: 201605878Z

Estimation

Date: Vehicle:

7/2/2023 SNB9433Z

Make / Model:

TOYOTA NOAH

Chassis No:

AIG

11	_	Chas	sis No:		AIG	
1	L	No. Description	Unit	Unit Price	Amount	
		Parts Replacement:	15 1 1		100 100 100 100 100 100 100 100 100 100	
		1 FRONT BUMPER	1	\$ 1,985.00	\$ 1,985.00	7
	_	2 FRONT BUMPER LOWER GARNISH	1	\$ 412.00	\$ 12.00	X
	_	FRONT BUMPER SPONGE	1	\$ 298.00	\$ 298.00	7
	4	THOIRT BOWN EN KEINT ONCEIVENT	1	\$ 598.00	\$ 12 598.00	X
	17	THORT BOWN EN BRACKET	2	\$ 144.00	\$ 1288.00	X
	8	FRONT GRILLE FRONT GRILLE LOGO WITH SENSOR	1	\$ 788.00	\$ 788.00	7
	9	FRONT GRILLE LOGO WITH SENSOR FRONT GRILLE OUTER GARNISH	1	\$ 1,125.00	\$ 1,125.00	7
	10	A 11.15 TO 100 T	1	\$ 488.00	\$ 488.00	4
	11	HEADLAMP NIS MET		\$ 3,895.00	\$ 7,790.00	
	12	0.000	n 1	\$ 122.00	\$ 122.00	X
	13		1 1	\$ 798.20	\$ 798.20	~
	14		N N N N N N N N N N N N N N N N N N N	\$ 83.20	\$ 166.40	X
	15	DEAD DUBARED TOMBER		\$ 171.45	\$ 324.40	4
	16	REAR BUMPER SENSOR WIRE HARNESS	1	\$ 45.00	\$ 45.00	7
	17		1	\$ 387.00	\$ 387.00	101
	18	TAU CATE ININIED TOUR	7 17 17 17 17 17 17 17 17 17 17 17 17 17	\$ 2,110.25	\$ 2,110.25	_
	19			\$ 589.00	\$ 589.00	-
	20	TAILGATE "HYBRID SYNERGY DRIVE LOGO"	14 1	\$ 141.10	\$ 141.10	1
H	21	TAILGATE OUTER CHROME MOULDING C/W SENSOR	-	\$ 741.00	\$ 741.00	
H	22	TAILGATE WEATHERSTRIPE	1	\$ 391.05	\$ 391.05	7
ŀ		TAILGATE LOCK	, 1	\$ 512.00	\$ 512.00	
H	23	TAILGATE LOCK CATCH	1	\$ 42.30	\$ 42.30	7
\perp	24	TAILGATE INNER SIDE GARNISH	2	\$ 159.00	\$ 318.00	1
_	25	TAILGATE WINDSCREEN GLASS Shotter	1	\$ 1,359.00	\$ 1,359.00	
-	26	TAILGATE WINDSCREEN MOULDING (SET)		\$ 387.00	\$ 387.00	_
L	27	TAILGATE DETECTOR	1	\$ 287.00	\$ 287.00	N
2	28	TAILGATE BUZZER	1	\$ 198.00		
2	9				7 250101	_
3	0	7 A A A A A A A A A A A A A A A A A A A		\$ 712.00		\cup \times
3			1	\$ 212.00	\$ 212.00) X
32	-	TAILGATE INNER CENTRE GARNISH	1	\$ 321.00	\$ 321.00	0 2
_	$\overline{}$	TAILGATE INNER SIDE GARNISH	2	\$ 212.00	\$ 424.00	0 7
33		TAILGATE NUMBER PLATE LAMP	2	\$ 68.00		
34		TAILGATE OUTER LOCK SENSOR	1	\$ 322.00		
35		TAILAMP		11.		_
36		TAILAMP LOWER PANEL (OUTER)	2	\$ 1,015.00		_
37		TAILAMP LOWER PANEL (COLLER)	2	\$ 359.00		The second second
38	_	TAILAMP LOWER PANEL (INNER)	2	\$ 312.00	\$ 624.0	0 7
_		TAILAMP LOWER GARNISH	1	\$ 451.00		
39		REAR FENDER N	2	\$ 1,587.00	· · · · · · · · · · · · · · · · · · ·	_
0		DEAD FEATOED MANAGE				
		REAR FENDER INNER TRIM LOWER	2	\$ 1,125.00	\$ 2,250.0	0 2

				3 /	T	N	596.00	X		
17	41 REAR FENDER INNER TRIM TOP	Sm			A STATE OF THE PARTY OF THE PAR	\$ \$	428.00	XX		
	REAR FENDER COWLING	In.	2	Total Control		\$	159.00	-5		
	REAR FENDER QUARTER GLASS MOULDING RH	32	1			\$	68.00	×		
35.55	REAR FENDER AIR VANT RH	5m	1	and the same of th		\$	2,258.00	X		
	REAR AIRCON BLOWER	1 Pu	$\frac{1}{2}$	Andread		\$	996.00			
100	SLIDING DOOR RAILING TOP GARNISH	B	1	The state of the state of		\$	689.20	12		
100	REAR END PANEL (OUTER)	121	1	No. of Lot, Spinster, Spinster,		\$	685.00	7.17		
4	REAR END PANEL (INNER)	13	$\frac{1}{\sqrt{1}}$		391.45	\$	391.45			
4	9 REAR END PANEL TOP GARNISH		1	\$ 2,4	489.00	\$	2,489.00			
5	0 REAR FLOOR PANEL	-1	1		241.00	\$	1,241.00			
5:	1 REAR FLOOR PANEL TOP BOARD SET	PL.	1	\$ 4	412.00	\$	412.00	-		
52	EXHALICT DIDE	n	1	T	359.00	\$	1,359.00			
53	THE PROPERTY OF THE PROPERTY O	n	1		321.00	\$	321.0	_		
54	ACLINITING	Su	2	\$	32.20	\$	64.4			
55	CDARE DOLT	Su	1	\$	32.00	\$	32.0	\rightarrow	X	
56	TO THE TOTAL TO A V	-:"	1		214.00	\$	214.0	Э.	7	
57	DEAD DATTERY	185	1	T .	450.00	\$	450.0	\sim	7	
58	THE STATE ASSIVED L		1	T	,857.00	-	4,857.0	30	7	
59	THE CHASSIS EXTENSION	-	2		387.00	\$	774.0	00	X	
60		1		1		\$	52,438.7		Y	
	TOTAL PART	and of a	250/	12:00	10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$	13,109.			
	LIST DOWN	100	25%			\$				
	AFTER LIST DOWN	¥ 11	10	12 - 12	Maria Company	+,	22,323.			
			12.00	and the second	E	-	to the same		1	
	S/N			1. A	00	+-		00	1	
1	FRONT BUMPER CLIPS		1	\$	80.00			.00	4	
2	FRONT NUMER PLATE WITH CASING	J.		\$	100.00	_		_	X	Ssa
3	REAR NUMBER PLATE	3)	1	\$	50.00	_	1 00 4 50 7 10 10 10 10	.00	10.	-JW
4	REAR CARRIER	Ry	1	\$	600.00			_	1-	•
5	REAR CAMERA	1000	1	\$	300.00	_		0.00	┥ .	,
6	TAILAMP CLIP SET	M	Sub-	\$	30.00	_		0.00	_	_
_	REAR BUMPER REVERSE SENSOR	NUP		\$	220.00	_		0.00	$\exists x$	
7	REAR BUMPER REVERSE SENSOR REVERSE CAMERA		1	\$	350.00	_	•	0.00	100	
8		ne	1	\$	50.00	_		0.00	_	
9	REAR BUMPER CLIP			\$	80.00	_		0.00	7	tosa
lo	TAILAGTE WINDSCREEN SEALANT	Me an				_			\mathcal{H}_{i}	BOIL
1	TAILAGTE WINDSCREEN INNER SEAL	M	-	\$	80.0	_	•	0.00		NA
2	TAILGATE OUTER MOULDING CLIPS SET	ne		\$	30.0	_		0.00	_	
3	TAILGATE INNER TRIM BOARD CLIPS SET	M	1	\$	50.0	_	•	0.00	، <u>ا</u> و	— _
4	REAR FENDER INNER TRIM BOARD CLIP SET	m		\$	50.0	100	\$ 10	0.00		
5	REAR FENDER INNER COWLING CLIPS SET	nn		\$	50.0	_		00.00		X
5 6	REAR END PANEL SEALANT	Ne	-	\$	120.0	_		20.0		301m
_	REAR END PANEL SEALANT	M	1	\$	30.0	_		30.0		
7				_		_				X
3	REAR FENDER GLASS SEALANT	nn	_	\$	80.0	_		80.0		
1	REAR BATTERY	Ph	1	\$	200.0			00.0	$\overline{}$	X
	TOOLS SET	92	1	\$		_	•	0.00		X
	REAR TOP MAT	U U	1	\$	300.0	00	\$ 3	00.0	00	1
\top	TOTAL SPECIAL NETT	J		1			-	50.0	-	
+	Labour to:FRONT AND REAR	1.03		\top			1	1	\dashv	١
+			1	1	300.	00	\$ 3	300.0	ᆔ	180
+	RESET TROUBLE CODE		1	_					_	7
!HE	ECK AND RESET FAULT CODE LIGHT ON HYBRID B	ATTE	R 1	\$	500.	UO	\$ 5	0.00	UU	1

3	REMOVE AND REFIT REAR WINDSCREEN G	LASS	1	\$ 150.00	\$	150.00	1201
4	REMOVE AND REFIT REAR SEAT, UPHOLT		1	\$ 400.00	\$	400.00	1201
5	REMOVE AND REFIT REAR AIRCON BLOW		1	\$ 150.00	\$	150.00	7
6	REMOVE AND REFIT REAR REVERSE SENS		. 1	\$ 120.00	\$	120.00	X
_			√ 2	\$ 80.00	\$	160.00	X
7	REMOVE AND REFIT REAR FENDER GLAS		-	\$ 150.00	\$	150.00	X
8	REMOVE AND REFIT REAR EXHAUST SYST		1	\$ 150.00	\$	150.00	601
9	REMOVE AND REFIT TAILGATE MECHANI	SIVI	_	\$ 200.00	\$	200.00	
10	TO CHECK ELECTRICAL WIRING		1	-	\$	200.00	-1 '
11	REAR CHASSIS REALIGNMENT	N	_		-		
12	PANEL BEATING ON AFFECTED AREA		1	\$ 3,400.00	\$	3,400.00	-1
13	SPRAY ON AFFECTED AREA		1	\$ 3,400.00	_	3,400.00	12001
				1	\$	9,280.00	□
				1			
		Parts Replacement Amount				42,479.06	Π
		\$	9,280.00				
	V.	13	3,200.00	^ \			
	*	\$	51,759.0				
Total Amount							5

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/atter spray painting
- To display damaged partis) auring resurvey
- Parts prices are subject to confirmation
- Third party survey is colar William Frejudice basis.
- No illegal modification(s) is an iver-
- Supplementary items) must be not may yet god is subject to final approval from insurance Contract

Acknowledged by Repairer

Signature:

Date:

SJ0G2321000A-01 / JP Knights Pte Ltd ENTRY DATE & TIME: 01/02/2023 10:17 (SGT) SUBMITTED BY: Siti VERSION: 2 (03/02/2023 11:39 (SGT))

C SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims proces
 This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>
 Information provided must be as truthful and accurate as possible. Any wilful mis ion or witholding of material facts may allow insurance compan policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. Any false reporting may be referred to the Police for Investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 01/02/2023 10:17 (SGT) Reported by Driver **Date of Accident** 30/01/2023 07:30 (SGT) **Exact Location of Accident** SLE, Singapore (BKE) BEFORE MANDAI ROAD EXIT Additional Location Information

DETAILS OF OWN VEHICLE

Singapore

Vehicle Registration Number **SNB9433Z**

INSURED/POLICYHOLDER

Country/State of Loss

Is company? Yes Name Of Registered Owner **LUMENS PTE LTD** Company Reg No 2XXXXX961K **Email Address** kokhow.tay@lumens.sg Mobile Phone No (Phone) +65-83866977 Alternative Phone No. (Office) +65-87781765

VEHICLE PARTICULARS

Manufacturer Toyota Model Noah Variant Exact purpose for which vehicle was being used at time of accident Private hire Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private hire **Transmission Auto** CC 1797

INSURANCE COMPANY

Name of Insurance Company **Tokio Marine Insurance Singapore Ltd** Policy Number / Cover Note Number 22-MN000813-R00

DRIVER

Name of Driver **MUHAMMAD ZAKI BIN MAKRUF** NRIC No SXXXX641A Date Of Birth 10/01/1975 Occupation Outdoor

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3, Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that:

- (a) My Insurer , my workshop and the General Insurance Association of Singapore (GIA*) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the daims
- (ii) investigating the accident and/or my claims.
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (M) administering my claims (including the mailing of correspondence, statements, invoices, reports, or notices to me, which could involved isclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (Collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect. use disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is/not the policyholder) / Date & Time 31/01/2023 2030hrs

FLASH ACCIDENT REPORTING OFFICER

FRO LATIFF

Witnessed by Reporting Centre Personne

Sketch Plan

