



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: NO:60 JALAN LAM HUAT CARROS CENTRE #05-68 SINGAPORE 737869

HP: 98888885/97816380

Estimation

Date:

8/2/2023

Vehicle:

SNE5759U

Make / Model:

TOYOTA NOAH

Chassis No:

No.	Description	Unit	Unit Price	Amount	
1	SLIDING DOOR LH	1	\$ 2,259.45	\$ 2,259.45	Rx
2	REAR FENDER LH	1	\$ 1,598.00	\$ 1,598.00	Rx
3	REAR BUMPER	1	\$ 798.00	\$ 798.00	Rx
	TOTAL PART			\$ 4,655.45	
	LIST DOWN	25%		\$ 1,163.86	
	AFTER LIST DOWN			\$ 3,491.59	
	SPECIAL NETT				
1	REAR DOOR STICKER NEC	1	\$ 200.00	\$ 200.00	150
2	REAR SPORTS RIM LH Scratch	1	\$ 600.00	\$ 600.00	Rx 100
				\$ 800.00	250
	LABOUR				
1	TO CHECK ELECTRICAL WIRING	1	\$ 50.00	\$ 50.00	K 111
2	ANTI RUST COAT	1	\$ 150.00	\$ 150.00	K 111
3	PANEL BEAT EFFECTED AREAS	1	\$ 600.00	\$ 600.00	300 1000
4	SPRAY PAINT ACCIDENT AREAS	1	\$ 800.00	\$ 800.00	700
	TOTAL AMOUNT			\$ 1,600.00	
Parts Replacement Amount				\$ 3,491.59	
Total Amount for Labour				\$ 2,400.00	
Total Amount				\$ 5,891.59	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97415749 1250
WP- 8/2/23 R 1240 1/4 1000
Taufik C / Khantaw 03 days
03 days
Ready after repair