



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD

INCOME CENTRESINGAPORE 189557

ATTN: JEFF LIN

Ref: CS/INC23001292/Kqy3m4

Date: 14/02/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 5121R	Veh. Inspected	GBF 2107H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1208188-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	07/02/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KDY2318024305	Colour	SILVER
Odometer	136067 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195R 15X8	BRIDGESTONE	9 mm
L/H Front Tyre	195R 15X8	BRIDGESTONE	9 mm
R/H Rear Tyre	155R 12X8 (D)	YOKOHAMA	9/9 mm
L/H Rear Tyre	155R 12X8 (D)	YOKOHAMA	9/9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/12/2022	Inspect Date / Time	07/02/2023 (12:28 PM)
Survey held at	FORZA AUTOHAUS PTE. LTD. 39 WOODLANDS CLOSE #01-34 MEGA@WOODLANDS SINGAPORE 737856		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days