

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC23001297/Uwy3e2	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	14/02/2023	
	ATTN: DAVID PHU	Α		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMX 6705E	Veh. Inspected		FBP 7913L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1207614-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		07/02/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA PCX 150	c.c		149	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	MH1KF2216KK083122	Colour		BLACK	
	Odometer	66643 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	100/80-14	PIRELLI		7 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	120/70-14	PIRELLI		7 mm	
	L/H Rear Tyre				mm	
4.	1. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
					ş*	
5.	. General Information					
	Accident Date	29/01/2023	Inspect Date /	Time	07/02/2023 (11:55 AM)	
	Survey held at	EROFIA MOTOR TRADING PTE	LTD			
		1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				