

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	ALLIANZ INSURA	NCE SINGAPORE PTE LTD		Ref:	CS3/AIS23001305/Wqy3
	79 ROBINSON RC #09-01 SINGAPOR			Date:	07/02/2023
				Code:	AIS
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMF 2992M	Veh. Inspected		SLG 1025T
	Policy No.		Coverage (\$)		0.00
	Claim No.	2023 32005295	Excess (\$)		0.00
	Assign From	SHANTI	Assign Date		07/02/2023
2.	. Vehicle Particulars & Condition				
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5.	General Information				
	Accident Date	03/02/2023	Inspection Date	е	08/02/2023
	Survey held at	BENEFIT AUTO CARE PTE LTD)		
	11 KAKI BUKIT ROAD 1 #01-02 SINGAPORE 415939				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				