

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/02/2023



User ID : JeongCH

Section A - Accident Details

Registration Number	SMB1584K
Case Reference Number	BUS/01/23/5007
Registration Date	12/30/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Zheng Dengshuai
Type of Accident	Head to Rear
Accident Date and Time	1/9/2023 8:35 AM
Accident Reported Date and Time	1/17/2023 10:00 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SMB1584K - REAR LEFT PORTION SMK9191Z (TP) - INSURED WITH CHINA TAIPING
Prepared Date and Time	2/7/2023 11:01 AM
Chassis Number	WMAA22ZZ7F7002553
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$0.00
Total Spray Cost	\$708.00	\$0.00
Total Spare Part Cost	\$701.78	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,939.78	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	07/02/2023 11:03 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/02/2023

User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$530.00						
Total Labour			\$530.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$708.00						
Total Spray Painting & Panel Beating			\$708.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010060	Body	F01001-CW271	COVER:REAR TAIL LAMP,LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	
Total					\$974.70		\$877.23		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									