



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23001346/Rqy3e2	
			Date: 23/03/2023	
			Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLM 4284K	Veh. Inspected	SNG 8165C	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS23/0444	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	08/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA NOAH HYBRID 1.8X CVT	c.c	1797	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	ZWR900010178	Colour	BLACK	
Odometer	33335 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TOYO	6 mm	
L/H Front Tyre	205/60 R16	TOYO	6 mm	
R/H Rear Tyre	205/60 R16	TOYO	6 mm	
L/H Rear Tyre	205/60 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/01/2023	Inspection Date	08/02/2023	
Survey held at	AUTOSPRINT PTE LTD 24 LENG KEE ROAD #07-01/02 LENG KEE AUTOPOINT SINGAPORE 159096			
5a. Remarks				
A)REGISTRATION DATE: 06 SEP 2022 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	