



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:CYNTHIA		Ref: CC4/HSB23001360/Kpa3q2 Date: 05/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3808B	Veh. Inspected	SML 3999G
Policy No.	P2478218	Coverage (\$)	0.00
Claim No.	S3M04IPU	Excess (\$)	0.00
Assign From		Assign Date	08/02/2023
2. Vehicle Particulars & Condition			
Make & Model	KIA SELTOS (A)	c.c	1353
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	MZBEP811VLN123613	Colour	METALLIC PEARL WHITE
Odometer	32073 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	7 mm
L/H Front Tyre	215/60 R16	MICHELIN	7 mm
R/H Rear Tyre	215/60 R16	MICHELIN	7 mm
L/H Rear Tyre	215/60 R16	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/01/2023	Inspection Date	20/02/2023
Survey held at	FORZA AUTOHAUS PTE. LTD. 39 WOODLANDS CLOSE #01-34 MEGA@WOODLANDS SINGAPORE 737856		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	