



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23001361/Aqy3e2	
			Date: 21/03/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 3244Z	Veh. Inspected	SJP 2597D
	Policy No.	D22MTPCVE001973	Coverage (\$)	0.00
	Claim No.	CMTD2300530/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	08/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA STREAM	c.c	1799
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JHMRN68609S200348	Colour	SILVER
	Odometer	223864 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/02/2023	Inspection Date	09/02/2023
	Survey held at	AUTO UNITED SG PTE LTD 13 KAKI BUKIT ROAD 4, #03-29, BARTLEY BIZ CENTRE, SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		21 Working Days	