



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2002093149-01	Date of Loss:	03/02/2023
Vehicle Reg. No.:	SMH2079P	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	DONOVAN EU KUM CHUEN		
Make/Model:	TOYOTA HARRIER, 2.0 M GRADE (A)	Vehicle Reg. Date:	16/01/2019
Vehicle Colour:	Red		
Engine No:	8ARZ145724	Chassis No:	JTEZB3GH50J003772
Odometer:	9967 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	4,179.70
Miscellaneous Items	0.00
Labour	2,390.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,569.70
+ GST 8.00% (S\$)	525.58
Nett Amount (S\$)	7,095.28

This claim is handled by: **BILLY**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Feb 2023)

Parts: M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Mova Automotive Pte Ltd/SMH2079P/09/02/2023 08:52

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE	0.00	0.00	*780.00 F
2	1		*TAILGATE GLASS MOULDING	0.00	0.00	*120.00 F
3	1		*TAILGATE GLASS SEALANT	0	0.00	*40.00 FS
4	1		*TAILGATE REFLECTOR RH	0.00	0.00	*230.00 F
5	1		*TAILGATE EMBLEM - HARRIER	0.00	0.00	*55.00 F
6	1		*TAILGATE EMBLEM - TURBO	0.00	0.00	*45.00 F
7	1		*TAILGATE WEATHERSTRIP	0.00	0.00	*145.00 F
8	1		*REAR FENDER RH	0.00	0.00	*580.00 F
9	1		*REAR QUARTER GLASS MOULDING GLASS RH	0.00	0.00	*580.00 F
10	1		*REAR QUARTER GLASS SEALANT RH	0	0.00	*40.00 FS
11	1		*TAILLAMP ASSY RH	0.00	0.00	*275.00 F
12	2		*TAILLAMP CLIPS	0.00	0.00	*14.00 F
13	1		*TAILLAMP PANEL RH - REPAIR	0.00	0.00	-
14	1		*REAR BUMPER	0.00	0.00	*380.00 F
15	1		*REAR BUMPER LOWER GARNISH	0.00	0.00	*260.00 F
16	1		*REAR BUMPER RETAINER RH	0.00	0.00	*18.00 F
17	10		*REAR BUMPER CLIPS	0.00	0.00	*20.00 F
18	1		*REVERSE SENSOR RH	0.00	0.00	*225.00 F
19	1		*REAR END PANEL - REPAIR	0.00	0.00	-

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,807.00
+ Margin on L,N Items 10.00% (\$\$)	372.70
Total Parts (\$\$)	4,179.70

Mova Automotive Pte Ltd/SMH2079P/09/02/2023 08:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CUT/ WELD REAR FENDER RH. KNOCK AND STRAIGHTEN TAILLAMP PANEL RH, REAR END PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	New	1,000.00
2	SPRAY PAINT TAILGATE, TAILLAMP PANEL RH, REAR END PANEL, REAR FENDER RH, REAR BUMPER	New	1,000.00
3	REMOVE & REPLACE TAILGATE GLASS AND CHECK WATER LEAKAGE	New	120.00
4	REMOVE & REPLACE TAILGATE INNER TRIM, MECHANISM AND CHECK LOCKING SYSTEM	New	60.00
5	REMOVE & REAPLACE REAR FENDER INNER TRIM RH, GARNISH, UPHOLSTERY, REAR SEAT AND REAR FLOOR CARPET	New	150.00
6	REMOVE & REPLACE REVERSE SENSOR AND CHECK FUNCTION	New	60.00
Gross Labour Cost (S\$)			2,390.00

Mova Automotive Pte Ltd/SMH2079P/09/02/2023 08:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >