


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: 6BE 5152L
 at Workshop m/s: huoh hoke 3pm
 of _____
 Insured: SNF 6920H
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: 35k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS C 247d
 Date: _____ Person Contacted: 17A 13244 Vehicle: IN / OUT

Veh No: 6BE 5152L Yr Regn: 23/12/15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (M)
 Make: Toyota hiace c.c. 2982
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp.Reading: 321375 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFHT02P 800187239
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195 R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 07/02/23 D.O.I. 14/02/23
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Rep.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>23/2/23</u>	<u>1/s \$1600 in bond bond (Red. \$8166.30, 84%)</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 3
 Resurvey No. of Trip: 1

1) 24/2/23
 Date/Time, File Return to?

Survey Fee: _____
 Transportation: _____
) S + RS, SI
) Photos
) Others
 TOTAL

Report Format : TP
 Lump Sum / I.B.I: (\$) 1600

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	247D
Vehicle Details	
Vehicle No.:	GBE5152L
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Feb 2023
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2580946
Chassis No.:	JTFHT02P800187239
Maximum Power Output:	-
Open Market Value:	\$27,741.00
Original Registration Date:	23 Dec 2015
First Registration Date:	23 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$1,388.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Dec 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$48,101.00
COE Rebate Amount:	\$13,744.00
Total Rebate Amount:	\$13,744.00

The information contained herein is correct as at 13 Feb 2023

OK

Post an Advertisement
 Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Low Interest Rate In-House Loan by GV Cars Financing



\$0 Downpayment. 90% Loan by
 GV Cars Financing at 3.28% p.a.
 Low Interest Rate
 GV Automobile Centre StarAd



Sort by results/page

17 vehicles



HIACE

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	HIACE		Any	Any	2015	Any	Any	Any	Available
	Toyota	Hiace 3.0M	\$38,800	\$15,680 /yr	05-Aug-2015	2,982 cc	115,328 km	Van	Available
		Fuel Type: Diesel							
		Most reliable model! Excellent condition, healthy engine and gearbox! Definitely a worry free unit! Full cash or loan very welcome! 100% loan no problem! We offer highest trade in for your current vehicle! Call for viewing or test drive now!							
		ABWIN (1994) Pte Ltd Posted: 12-Feb-2023							
	Toyota	Hiace Commuter 3.0A	\$39,800	\$14,960 /yr	12-Oct-2015	2,982 cc	-	Bus	Available
		Fuel Type: Diesel							
		Just arrived. 11 passengers capacity with own install rear aircon done. New paintwork done. Engine gearbox under good condition. High loan available. Contact our friendly salesman for viewing and test drive.							
		ABS Bus Pte Ltd Posted: 07-Feb-2023							
	Toyota	Hiace 3.0M	\$32,800	\$15,590 /yr	23-Mar-2015	2,982 cc	167,310 km	Van	Available
		Fuel Type: Diesel							
		Very Well Maintained Toyota Hiace. Best Investment For Short Term Usage. Can Further Extend 10 Years COE. Reliable And Powerful.Bestfor Delivery Or Construction Usage. Call Now To Find Out More.							
		Posted: 05-Feb-2023							
	Toyota	Hiace Commuter 3.0A GL	\$50,000	\$23,610 /yr	28-Mar-2015	2,982 cc	-	Bus	Available
		Fuel Type: Diesel							
		Good condition PI Euro 5 Toyota Hiace commuter, fresh new white spray paint, newly changed tyres.							
		Posted: 02-Feb-2023							
	Toyota	Hiace 3.0M	\$30,800	\$15,440 /yr	11-Feb-2015	2,982 cc	-	Van	Available
		Fuel Type: Diesel							
		Luxurious body kit! Enhanced sound system. Perfect for newly start up business. No repairs needed. Well taken care and refurbished by previous owner. What you see is what you get. No Gimmicks. Contact us now for test drive and viewing!							
		SG Motor Link Pte Ltd Posted: 30-Jan-2023							
	Toyota	Hiace 3.0M	\$32,800	\$15,100 /yr	17-Apr-2015	2,982 cc	133,000 km	Van	Available
		Fuel Type: Diesel							
		1 owner, low mileage, very well maintained, accident free, excellent condition! Ideal for short term use or COE renewal! Flexible bank/high loan financing schemes with competitive interest rates tailored to suit your needs! View to believe, pity to miss! WhatsApp/call/SMS sale...							
		Posted: 30-Jan-2023							
	Toyota	Hiace Commuter 3.0A	\$40,385	N.A	16-Sep-2015	2,982 cc	-	Bus	Available
		Fuel Type: Diesel							
		Very nicely well taken care of by former owner! Minibus 11+1 seater auto available now. Almost like new vehicle condition wait no more and give us a call to view.							
		Posted: 26-Jan-2023							

Compare



發 福 摩 哆 車 房
HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
 BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
 Tel / Fax: 6445 2934 Hp: 8161 6988
 BUSINESS REG NO. 375854/00C

Not Actual
 14/2/23
 1/5 @ 1600/
 3 days.
 take photo after repair

Carplate: GBE5152L
Chassis No: JTFHT02P800187239
Accident Date: 07/02/2023
Make & Model: Toyota HiAce

No.	Item	Nett Price	<input checked="" type="checkbox"/> / <input type="checkbox"/>	Remarks
1	Front Bumper	\$ 595.10		cut ✓
2	Front Bumper Side Retainer (LH)	\$ 114.30		cut ✓
3	Front Bumper Reinforcement Beam	\$ 429.10		17 X
4	Headlamp LH	\$ 718.20		cut ✓
5	Front Door LH	\$ 1,406.10		2 X
6	Front Door Hinge LH (Upper)	\$ 74.10		17 X
7	Front Door Hinge LH (Lower)	\$ 74.10		17 X
8	Front Door Check LH	\$ 120.10		17 X
9	Front Door LH Step-up Garnish	\$ 115.10		ground ✓
10	Front Door LH Step-Up Panel	\$ 435.00		2 X
11	Front Shock Absorber LH	\$ 325.90		17 X
12	Front Wheel Bearing LH	\$ 136.20		17 X
13	Front Wheel Hub LH	\$ 385.10		17 X
14	Front Lower Arm LH	\$ 149.20		17 X
15	Front Wheel Rim Cover LH	\$ 150.60		17 X
16	Front Door LH Trim Board	\$ 408.10		17 X
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				
35				
36				

(252)

	<u>Special Nett Items</u>	Price	<input checked="" type="checkbox"/> / <input checked="" type="checkbox"/>	Remarks
1	Front Bumper Clips (1set)	\$ 40.00		Net ✓
2	Front Door Trim Board Clips (1set)	\$ 40.00		17 X
3	Front Tyre LH	\$ 290.00		47 X
4	Front Tyre Rim LH	\$ 380.00		17 X
5	Front Door LH Sticker	\$ 580.00		Net 300
6	Front Door LH Company Sticker	\$ 50.00		Net 30
7				
8				
9				
10				
11				
No.	All Necessary Work	Price	<input checked="" type="checkbox"/> / <input checked="" type="checkbox"/>	Remarks
1	To Carry Out Anti-rust Treatment	\$ 120.00		17 X
2	Under Carriage Works (Including Removal of Shock absorber, Spring, Lower Arm, Wheel Hub, Brake Assembly, Wheel Bearing and all necessary)	\$ 380.00		17 X
3	Transfer of Front Door Mechanism	\$ 120.00		17 X
4	To Remove and Re-stick Sticker	\$ 250.00		17 X
5	4 Wheel Allignment	\$ 180.00		17 X
6	Labour to remove and replace damaged parts (Including refitting and repositioning of replaced parts)	\$ 800.00		300
7	Spray painting materials and respray of all affected and replaced parts necessary for paintwork	\$ 900.00		200
	Estimated No. of days for repairs and respray of all necessary	6 Days		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9766.30.

P-1542.7
 252
 1157.02
 370
 500
 2027.02
 20%
 1121