



# CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

## (SUPPLEMENTARY)

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

### PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/CHINA
Policy No:	DMCVSNW00107052202	Date of Loss:	01/02/2023
Vehicle Reg. No.:	<b>GBE1520J</b>	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GTS ENGINEERING PTE LTD		
Driver:	MASUD		

Make/Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Vehicle Reg. Date:	19/09/2015
Vehicle Colour:	GOLD		
Engine No:	ZD30001401N	Chassis No:	JN1SC2F24Z0857565
Odometer:	234856 KM		

Paint Type:	
Total Loss?	<b>NO</b>
Est. Duration of Repair (day)	0

Description of Accident/Loss REFER GIA REPORT ATTACHED  
Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

### COST OF CLAIMS

	<b>Amount</b>
Parts	395.00
Miscellaneous Items	0.00
Labour	1,480.00
Paintwork Labour	0.00
Towing	0.00
	<b>Gross Total (S\$) 1,875.00</b>
	<b>+ GST 8.00% (S\$) 150.00</b>
	<b>Nett Amount (S\$) 2,025.00</b>
	<b>+ Previous Estimates (S\$) 7,274.88</b>
	<b>Claim Total (S\$) 9,299.88</b>

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 24 Feb 2023)**Parts:** N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/GBE1520J/24/02/2023 18:58**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CRANKSHAFT PULLEY <span style="color: blue;">cracked</span>	0.00	0.00	*300.00 F
2	1		*L/F SHOCK ABSORBER <span style="color: blue;">bent</span>	0.00	0.00	*95.00 F
<b>Total Parts (S\$)</b>						<b>395.00</b>

F=Franchise part.

Cheng Hoe Motor Pte Ltd/GBE1520J/24/02/2023 18:58. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO STRAIGHTEN , KNOCK, REPAIR AND REALIGN RH MAIN CHASSIS	New	800.00 ✓
2	REMOVE AND REFIT ENGINE, GEARBOX(TO REPAIR MAIN CHASSIS)	New	280.00 250
3	REMOVE AND REFIT CRANK SHAFT PULLEY AND RESET ENGINE	New	200.00 x
4	REMOVE AND REFIT REAR CANOPY, REAR TRUCK.	New	200.00 ✓
<b>Gross Labour Cost (S\$)</b>			<b>1,480.00</b>

Cheng Hoe Motor Pte Ltd/GBE1520J/24/02/2023 18:58. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >