



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS3/LPC22010190/Sny3e2-1

Date: 28/02/2023

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 553R	Veh. Inspected	SKA 4862S
Policy No.	Z22VC05010002	Coverage (\$)	0.00
Claim No.	22/22/22/VC05/026416	Excess (\$)	0.00
Assign From	CHARMAINE KONG	Assign Date	07/02/2023

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 316I	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBA3A12050J720401	Colour	WHITE
Odometer	105022 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	MICHELIN	6 mm
L/H Front Tyre	225/45 R18	MICHELIN	6 mm
R/H Rear Tyre	225/45 R18	MICHELIN	6 mm
L/H Rear Tyre	225/45 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/10/2022	Inspection Date	14/10/2022
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.