



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC23000198/Tvy3e2-1 Date: 04/04/2023 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBJ 5346T	Veh. Inspected	SKB 7238U
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/23/23/VC05/026797	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	07/02/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ C180K	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	WDD2040452A426247	Colour	BLACK
	Odometer	154589 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	FALKEN	6 mm
	L/H Front Tyre	225/45 R18	FALKEN	6 mm
	R/H Rear Tyre	225/45 R18	FALKEN	6 mm
	L/H Rear Tyre	225/45 R18	FALKEN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	01/01/2023	Inspection Date	10/01/2023
	Survey held at	FDK AUTOMOBILE & LEASING SERVICES PTE LTD 39 WOODLANDS CLOSE #05-12 MEGA@WOODLANDS SINGAPORE 737856		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	