

## Xin Yu (LKK Auto)

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Wednesday, May 3, 2023 11:46 AM  
**To:** Xin Yu (LKK Auto)  
**Subject:** Re: File Audit - SMX 3283A - CS3/HSB23001444/Swp3

Dear Xin Yu,

AUDIT CHECK DONE FOR SMX3283A, FOUND COR RANGE IS 24K TO 28K, NOT ECONOMICAL TO REPAIR.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Xin Yu (LKK Auto) <xinyu@lkkauto.com>  
**Sent:** Wednesday, 3 May 2023 11:18 am  
**To:** Simon Ho (LKKAuto) <SimonHo@lkkauto.com>  
**Subject:** File Audit - SMX 3283A - CS3/HSB23001444/Swp3

Dear Simon,

File for audit check.

Best Regards,

**Xin Yu** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | fax: 6256-4315 | email: [xinyu@lkkauto.com](mailto:xinyu@lkkauto.com) / [sur@lkkauto.com](mailto:sur@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)