



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23001450/Sqy3m4 Date: 24/04/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLH 642M	Veh. Inspected	PC 3235P	
Policy No.	SI22V13319/VPC/R03/E00	Coverage (\$)	0.00	
Claim No.	IVS23/0204	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	10/02/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI ROSA	c.c	2998	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	BE641JJ10142	Colour	WHITE	
Odometer	276490 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/75R17.5	GOODTYRE	5 mm	
L/H Front Tyre	215/75R17.5	GOODTYRE	5 mm	
R/H Rear Tyre	215/75R17.5	GOODTYRE	5 mm	
L/H Rear Tyre	215/75R17.5	GOODTYRE	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/01/2023	Inspection Date	13/02/2023	
Survey held at	30 DEFU LANE 9 SINGAPORE 539270			
Repairer	BEDOK MOTOR ENGINEERING PTE LTD			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 16 DEC 2014 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	