



Bedok Motor Engineering Pte Ltd
30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
+65 6286 3032

Estimate To Repair PC3235P - MITSUBISHI ROSA BUS BE641JRMDEB

Chassis No : BE641JJ10142 /

S/No	Quantity	Description	Amount
1		<u>LABOUR & MISC CHARGE</u> Putty and spray painting on the affected portion. <i>panel beating 400 - 200</i>	\$ 2,200.00 <i>300</i>
		<i>FT = 500</i>	
		Total	\$ 2,200.00

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 days

45 P/D

1 item

13/2/23

11 am

90097659