



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23001463/Kvy3m4 Date: 26/05/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMB 1371H	Veh. Inspected	SKW 8859K
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/01/23/5009	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	10/02/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA RAV 4 (A)	c.c	1987
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JTMY43FV30J025111	Colour	M. P. WHITE
	Odometer	54290 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/60R18	BRIDGESTONE	7 mm
	L/H Front Tyre	225/60R18	BRIDGESTONE	7 mm
	R/H Rear Tyre	225/60R18	BRIDGESTONE	7 mm
	L/H Rear Tyre	225/60R18	BRIDGESTONE	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	09/01/2023	Inspection Date	13/02/2023
	Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	