



code  
 Reg No. : 196700086Z  
 SST Reg No. : MR-8500000-9  
 No. 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

| Account Details                                                                                                          |         |                                                                                                                                                                               | Account No.                 |                 | Customer Details                                                                           |            |                      |           |
|--------------------------------------------------------------------------------------------------------------------------|---------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-----------------|--------------------------------------------------------------------------------------------|------------|----------------------|-----------|
| Ergo Insurance Pte Ltd<br>5 Temasek Boulevard<br>#04-01 Suntec Tower Five<br>Singapore 038985<br>Attn: Motor Claims Dept |         |                                                                                                                                                                               | S1000010 / ICN13            |                 | M/S Manikarnika Pte Ltd<br>77 High Street<br>#01-09A High Street Plaza<br>Singapore 179433 |            |                      |           |
|                                                                                                                          |         |                                                                                                                                                                               | Document No.<br>0           |                 |                                                                                            |            |                      |           |
|                                                                                                                          |         |                                                                                                                                                                               | Document Date<br>09/02/2023 |                 |                                                                                            |            |                      |           |
| Year                                                                                                                     | Model   | Variant                                                                                                                                                                       | Reg. Date                   | Reg. No.        | Kilometers                                                                                 | Wip No.    | Order No. / Remarks  |           |
| 2022                                                                                                                     | GDY231R | TLMGV M1                                                                                                                                                                      | 20/12/2022                  | YQ9072Y         | 0                                                                                          | 20120      | 72/UL/YQ9072Y        |           |
| Chassis No.                                                                                                              |         | Engine No.                                                                                                                                                                    | Terms                       | SA / Counter    | Vehicle In                                                                                 |            | Collected On         |           |
| JHHAGV4620K003138                                                                                                        |         | 1GD9034948                                                                                                                                                                    | 60                          | Thomas Pang W T | --/--/----                                                                                 |            | 0.00 --/--/---- 0.00 |           |
| L                                                                                                                        | Cd      | Job/Parts Description                                                                                                                                                         |                             |                 | Qty                                                                                        | Unit Price | Disc %               | Amount    |
| 1                                                                                                                        | Z       | BP-SUNDRY SUNDRIES<br>POLICY NO.:DMCG22017213 ACC DATE:09.02.2023<br>TOW IN:09.02.2023 EXCESS:<br>DATE-IN:09.02.2023 DATE SURVEY:<br>NO OF REPAIR DAYS:<br>BY: AUTHORIZED ON: |                             |                 |                                                                                            |            |                      | 50 100.00 |
| 2                                                                                                                        | Z       | BP-SLANT SUPPLY SEALANT (NETT)                                                                                                                                                |                             |                 |                                                                                            |            |                      | 20 300.00 |
| 3                                                                                                                        | B       | BP-LAB2 REPLACE AND REFOCUS HEADLAMP                                                                                                                                          |                             |                 |                                                                                            |            |                      | 134.64    |
| 4                                                                                                                        | B       | BP-LAB2 R/I DASHBOARD ASSY TO FAC REPAIR.                                                                                                                                     |                             |                 |                                                                                            |            |                      | 1584.00   |
| 5                                                                                                                        | B       | BP-LAB2 R/I AC CON SYSTEM, BLOWER ASSY TO FAC REPAIR.                                                                                                                         |                             |                 |                                                                                            |            |                      | 792.00    |
| 6                                                                                                                        | B       | BP-LAB2 R/I WIRE HARNESS ASSY TO FAC REPAIR.                                                                                                                                  |                             |                 |                                                                                            |            |                      | 792.00    |
| 7                                                                                                                        | B       | BP-WS2 R/I FRONT WINDSCREEN GLASS TO FAC REPAIR                                                                                                                               |                             |                 |                                                                                            |            |                      | 594.00    |
| 8                                                                                                                        | B       | BP-LAB2 REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR                                                                                                                     |                             |                 |                                                                                            |            |                      | 396.00    |
| 9                                                                                                                        | B       | BP-LAB2 TO REPLACE BRAKE SYSTEM, BOOSTER ASSY..                                                                                                                               |                             |                 |                                                                                            |            |                      | 792.00    |
| 10                                                                                                                       | B       | BP-LAB2 TO REPLACE AIR BAG ASSY, CONTROL AND SENSOR..                                                                                                                         |                             |                 |                                                                                            |            |                      | 792.00    |
| 11                                                                                                                       | B       | BP-LAB2 TO REPLACE SAFETY BELT ASSY..                                                                                                                                         |                             |                 |                                                                                            |            |                      | 792.00    |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

| For & on behalf of                |  | Customer's Signature                  | Charge Summary    | Total      |
|-----------------------------------|--|---------------------------------------|-------------------|------------|
| Borneo Motors (Singapore) Pte Ltd |  | Please acknowledge receipt of vehicle | Parts             | Less       |
|                                   |  |                                       | Labour            |            |
|                                   |  |                                       | Sublet            | Amount Due |
|                                   |  |                                       | Lubrication/Fluid |            |
|                                   |  |                                       | Others            |            |

Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No. 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no.: 6631 1188

**ESTIMATE**

| Account Details                                                                                                          |  | Account No.                 | Customer Details                                                                           |  |  |  |
|--------------------------------------------------------------------------------------------------------------------------|--|-----------------------------|--------------------------------------------------------------------------------------------|--|--|--|
| Ergo Insurance Pte Ltd<br>5 Temasek Boulevard<br>#04-01 Suntec Tower Five<br>Singapore 038985<br>Attn: Motor Claims Dept |  | S1000010 / ICN13            | M/S Manikarnika Pte Ltd<br>77 High Street<br>#01-09A High Street Plaza<br>Singapore 179433 |  |  |  |
|                                                                                                                          |  | Document No.<br>0           |                                                                                            |  |  |  |
|                                                                                                                          |  | Document Date<br>09/02/2023 |                                                                                            |  |  |  |

  

| Year | Model   | Variant  | Reg. Date  | Reg. No. | Kilometers | Wip No. | Order No. / Remarks |
|------|---------|----------|------------|----------|------------|---------|---------------------|
| 2022 | GDY231R | TLMGV M1 | 20/12/2022 | YQ9072Y  | 0          | 20120   | 72/UL/YQ9072Y       |

  

| Chassis No.       | Engine No. | Terms | SA / Counter    | Vehicle In | Collected On         |
|-------------------|------------|-------|-----------------|------------|----------------------|
| JHHAGV4620K003138 | 1GD9034948 | 60    | Thomas Pang W T | --/--/---- | 0.00 --/--/---- 0.00 |

  

| L  | Cd | Job/Parts Description                             | Qty   | Unit Price | Disc % | Amount       |
|----|----|---------------------------------------------------|-------|------------|--------|--------------|
| 12 | B  | BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST       |       |            |        | nnX 134.64   |
| 13 | B  | BP-ECU2 TO RESET ECU AND REPROGRAMME              |       |            |        | 198.00       |
| 14 | B  | BP-LAB2 REPLACE REAR EXHAUST PIPE                 |       |            |        | 396 192.00   |
| 15 | L  | BP-LPO SUPPLY REGN PLATE (PO# )                   |       |            |        | 160.00       |
| 16 | B  | BP-LAB2 REPLACE ACC DAMAGED PARTS @ 792 X 7       |       |            |        | 5544 7920.00 |
| 17 | B  | BP-RES2 RESPRAY ACC AFFECTED AREAS @ 656 X 6      |       |            |        | 3936 5248.00 |
| 18 | S  | BP-SUBLET SUPPLY COMPANY DOOR BLACK STICKER- 2PCS |       |            |        | 100.00       |
| 19 | 1  | T51211-25120 CROSSMEMBER, FRAME, Lt               | 1.00  | 219.10     |        | 219.10       |
| 20 | 2  | T51202-25170 CROSSMEMBER Lt                       | 1.00  | 0.00       |        |              |
| 21 | 3  | T51103-25020 REINFORCEMENT ?                      | 1.00  | 0.00       |        |              |
| 22 | 4  | T51104-25010 REINFORCEMENT ?                      | 1.00  | 0.00       |        |              |
| 23 | 5  | T52101-37985 BUMPER SUB-ASSY, FR Torn             | 1.00  | 748.90     |        | 748.90       |
| 24 | 6  | T52011-37140 ARM SUB-ASSY, FR Lt                  | 1.00  | 364.10     |        | 364.10       |
| 25 | 7  | T52012-37140 ARM SUB-ASSY, FR Lt                  | 1.00  | 362.50     |        | 362.50       |
| 26 | 8  | T81481-37040 COVER, FOG LAMP, RH ?                | 1.00  | 75.60      |        | 75.60        |
| 27 | 9  | T81482-37040 COVER, FOG LAMP, LH ?                | 1.00  | 75.60      |        | 75.60        |
| 28 | 0  | T53111-37A70 B1 GRILLE, RADIATOR m/s              | 1.00  | 777.00     |        | 777.00       |
| 29 | 1  | T67771-37040 RETAINER, DOOR TRIM m/s              | 10.00 | 7.30       |        | 73.00        |
| 30 | 2  | T53142-37010 GARNISH, RADIATOR m/s                | 1.00  | 235.60     |        | 235.60       |
| 31 | 3  | T53115-37100 BRACKET, RADIATOR Lt                 | 1.00  | 26.30      |        | 26.30        |

  

|                                   |                                       |                                                          |            |
|-----------------------------------|---------------------------------------|----------------------------------------------------------|------------|
| For & on behalf of                | Customer's Signature                  | Charge Summary                                           | Total      |
| Borneo Motors (Singapore) Pte Ltd |                                       |                                                          |            |
|                                   | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others | Less       |
|                                   |                                       |                                                          | Amount Due |

# Borneo Motors



Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No. 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

| Account Details                                                                                                          | Account No.                                                                  | Customer Details                                                                           |
|--------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|
| Ergo Insurance Pte Ltd<br>5 Temasek Boulevard<br>#04-01 Suntec Tower Five<br>Singapore 038985<br>Attn: Motor Claims Dept | S1000010 / ICN13<br><br>Document No.<br>0<br><br>Document Date<br>09/02/2023 | M/S Manikarnika Pte Ltd<br>77 High Street<br>#01-09A High Street Plaza<br>Singapore 179433 |

| Year              | Model      | Variant  | Reg. Date       | Reg. No.   | Kilometers   | Wip No.    | Order No. / Remarks |
|-------------------|------------|----------|-----------------|------------|--------------|------------|---------------------|
| 2022              | GDY231R    | TLMGV M1 | 20/12/2022      | YQ9072Y    | 0            | 20120      | 72/UL/YQ9072Y       |
| Chassis No.       | Engine No. | Terms    | SA / Counter    | Vehicle In | Collected On |            |                     |
| JHHAGV4620K003138 | 1GD9034948 | 60       | Thomas Pang W T | --/--/---- | 0.00         | --/--/---- | 0.00                |

| L  | Cd | Job/Parts Description                       | Qty  | Unit Price | Disc % | Amount  |
|----|----|---------------------------------------------|------|------------|--------|---------|
| 32 | 4  | T53145-37040 CLIP, RADIATOR <i>m</i>        | 2.00 | 4.40       |        | 8.80    |
| 33 | 5  | T75392-37010 RETAINER, OUTSIDE <i>m</i>     | 6.00 | 0.00       |        |         |
| 34 | 6  | T90159-60259 SCREW <i>X</i> nn              | 2.00 | 3.00       |        | 6.00    |
| 35 | 7  | T93560-14012 SCREW <i>X</i> nn              | 2.00 | 2.60       |        | 5.20    |
| 36 | 8  | T90467-10188 CLIP <i>m</i>                  | 6.00 | 3.40       |        | 20.40   |
| 37 | 9  | T75315-37080 ORNAMENT, RADIATOR <i>rec</i>  | 1.00 | 84.60      |        | 84.60   |
| 38 | 0  | T75311-37290 PLATE, FR NAME, NO.1 <i>m</i>  | 1.00 | 53.10      |        | 53.10   |
| 39 | 1  | T53143-37010 GARNISH, RADIATOR <i>m</i>     | 1.00 | 57.00      |        | 57.00   |
| 40 | 2  | T56121-25040 WEATHERSTRIP, <i>m</i>         | 1.00 | 443.40     |        | 443.40  |
| 41 | 3  | T55078-37110 COVER SUB-ASSY, FR <i>bt</i>   | 1.00 | 374.20     |        | 374.20  |
| 42 | 4  | T55738-37080 PROTECTOR, FR PANEL <i>m</i>   | 1.00 | 109.50     |        | 109.50  |
| 43 | 5  | T55700-37460 COWL ASSY <i>bt</i>            | 1.00 | 1434.30    |        | 1434.30 |
| 44 | 6  | T53813-37170 B0 PANEL, FR SIDE, RH ?        | 1.00 | 392.50     |        | 392.50  |
| 45 | 7  | T55785-37070 PAD, FR PANEL COVER ?          | 1.00 | 0.00       |        |         |
| 46 | 8  | T53814-37100 B1 PANEL, FR SIDE, LH <i>m</i> | 1.00 | 404.20     |        | 404.20  |
| 47 | 9  | T55785-37070 PAD, FR PANEL COVER <i>m</i>   | 1.00 | 0.00       |        |         |
| 48 | 0  | T90467-10162 CLIP <i>m</i>                  | 6.00 | 3.40       |        | 20.40   |
| 49 | 1  | T55735-37021 REINFORCEMENT, COWL ?          | 1.00 | 47.90      |        | 47.90   |
| 50 | 2  | T55736-37021 REINFORCEMENT, COWL ?          | 1.00 | 47.90      |        | 47.90   |
| 51 | 3  | T53827-37010 PROTECTOR, FR FENDER <i>m</i>  | 2.00 | 54.20      |        | 108.40  |

| For & on behalf of                | Customer's Signature                  | Charge Summary                                           | Total              |
|-----------------------------------|---------------------------------------|----------------------------------------------------------|--------------------|
| Borneo Motors (Singapore) Pte Ltd | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others | Less<br>Amount Due |

Reg No. : 196700086Z  
 Reg No. : MR-8500000-9  
 #2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

| Account Details                                                                                                          | Account No.                 | Customer Details                                                                           |
|--------------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------------------------|
| Ergo Insurance Pte Ltd<br>5 Temasek Boulevard<br>#04-01 Suntec Tower Five<br>Singapore 038985<br>Attn: Motor Claims Dept | S1000010 / ICN13            | M/S Manikarnika Pte Ltd<br>77 High Street<br>#01-09A High Street Plaza<br>Singapore 179433 |
|                                                                                                                          | Document No.<br>0           |                                                                                            |
|                                                                                                                          | Document Date<br>09/02/2023 |                                                                                            |

| Year              | Model      | Variant  | Reg. Date       | Reg. No.   | Kilometers   | Wip No.    | Order No. / Remarks |
|-------------------|------------|----------|-----------------|------------|--------------|------------|---------------------|
| 2022              | GDY231R    | TLMGV M1 | 20/12/2022      | YQ9072Y    | 0            | 20120      | 72/UL/YQ9072Y       |
| Chassis No.       | Engine No. | Terms    | SA / Counter    | Vehicle In | Collected On |            |                     |
| JHHAGV4620K003138 | 1GD9034948 | 60       | Thomas Pang W T | --/--/---- | 0.00         | --/--/---- | 0.00                |

| L  | Cd | Job/Parts Description                      | Qty   | Unit Price | Disc % | Amount  |
|----|----|--------------------------------------------|-------|------------|--------|---------|
| 52 | 4  | T67002-37323 PANEL SUB-ASSY, FR <i>bt</i>  | 1.00  | 2021.40    |        | 2021.40 |
| 53 | 5  | T68610-37030 CHECK ASSY, FR DOOR <i>?</i>  | 1.00  | 220.60     |        | 220.60  |
| 54 | 6  | T68730-37010 HINGE ASSY, FR DOOR, <i>?</i> | 1.00  | 132.30     |        | 132.30  |
| 55 | 7  | T68710-37020 HINGE ASSY, FR DOOR, <i>?</i> | 1.00  | 132.30     |        | 132.30  |
| 56 | 8  | L90269-04051 RIVET <i>wt</i>               | 10.00 | 1.80       |        | 18.00   |
| 57 | 9  | T90269-06013 RIVET <i>wt</i>               | 10.00 | 2.40       |        | 24.00   |
| 58 | 0  | T81110-37660 HEADLAMP ASSY, RH <i>cm</i>   | 1.00  | 1412.70    |        | 1412.70 |
| 59 | 1  | T81150-37660 HEADLAMP ASSY, LH <i>cm</i>   | 1.00  | 1412.70    |        | 1412.70 |
| 60 | 2  | T86520-25150 HORN ASSY, LOW <i>?</i>       | 1.00  | 162.10     |        | 162.10  |
| 61 | 3  | T87010-25070 UNIT ASSY, AIR <i>?</i>       | 1.00  | 0.00       |        |         |
| 62 | 4  | T87210-37100 CASE ASSY, AIR <i>?</i>       | 1.00  | 405.80     |        | 405.80  |
| 63 | 5  | T44610-25350 BOOSTER ASSY, BRAKE <i>?</i>  | 1.00  | 1892.30    |        | 1892.30 |
| 64 | 6  | T44704-25160 RESERVOIR SUB-ASSY, <i>?</i>  | 1.00  | 280.70     |        | 280.70  |
| 65 | 7  | T52105-25040 BUMPER SUB-ASSY, RR <i>bt</i> | 1.00  | 997.80     |        | 997.80  |
| 66 | 8  | T52151-25050 STAY, RR BUMPER, RH <i>bt</i> | 1.00  | 314.60     |        | 314.60  |
| 67 | 9  | T52152-25020 STAY, RR BUMPER, LH <i>bt</i> | 1.00  | 314.60     |        | 314.60  |
| 68 | 0  | T91552-11430 BOLT, FLANGE <i>?</i>         | 3.00  | 0.00       |        |         |
| 69 | 1  | T90179-14007 NUT <i>?</i>                  | 3.00  | 5.90       |        | 17.70   |
| 70 | 2  | T91552-01225 BOLT, FLANGE <i>?</i>         | 3.00  | 4.60       |        | 13.80   |
| 71 | 3  | T51961-36040 HOOK <i>?</i>                 | 1.00  | 128.90     |        | 128.90  |

| For & on behalf of                | Customer's Signature                  | Charge Summary                                           | Total              |
|-----------------------------------|---------------------------------------|----------------------------------------------------------|--------------------|
| Borneo Motors (Singapore) Pte Ltd | Please acknowledge receipt of vehicle | Parts<br>Labour<br>Sublet<br>Lubrication/Fluid<br>Others | Less<br>Amount Due |



Reg No. : 196700086Z  
 Reg No. : MR-8500000-9  
 No. 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

| Account Details                                                                                                  | Account No.                 | Customer Details                                                                           |
|------------------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------------------------|
| go Insurance Pte Ltd<br>Temasek Boulevard<br>4-01 Suntec Tower Five<br>Singapore 038985<br>tn: Motor Claims Dept | S1000010 / ICN13            | M/S Manikarnika Pte Ltd<br>77 High Street<br>#01-09A High Street Plaza<br>Singapore 179433 |
|                                                                                                                  | Document No.<br>0           |                                                                                            |
|                                                                                                                  | Document Date<br>09/02/2023 |                                                                                            |

| Year              | Model      | Variant  | Reg. Date       | Reg. No.   | Kilometers   | Wip No.    | Order No. / Remarks |
|-------------------|------------|----------|-----------------|------------|--------------|------------|---------------------|
| 2022              | GDY231R    | TLMGV M1 | 20/12/2022      | YQ9072Y    | 0            | 20120      | 72/UL/YQ9072Y       |
| Chassis No.       | Engine No. | Terms    | SA / Counter    | Vehicle In | Collected On |            |                     |
| JHHAGV4620K003138 | 1GD9034948 | 60       | Thomas Pang W T | --/--/---- | 0.00         | --/--/---- | 0.00                |

| L  | Cd | Job/Parts Description                       | Qty  | Unit Price | Disc % | Amount  |
|----|----|---------------------------------------------|------|------------|--------|---------|
| 72 | 4  | T81550-25110 LAMP ASSY, RR <i>ca</i>        | 1.00 | 278.70     |        | 278.70  |
| 73 | 5  | T81560-25100 LAMP ASSY, RR <i>ca</i>        | 1.00 | 278.70     |        | 278.70  |
| 74 | 6  | T75135-25091 BRACKET, COMBINATION <i>bt</i> | 1.00 | 71.30      |        | 71.30   |
| 75 | 7  | T75136-25041 BRACKET, COMBINATION <i>bt</i> | 1.00 | 69.90      |        | 69.90   |
| 76 | 8  | T17430-11A51 PIPE ASSY, EXHAUST <i>bt</i>   | 1.00 | 839.70     |        | 839.70  |
| 77 | 9  | T17420-11800 PIPE ASSY, EXHAUST <i>?</i>    | 1.00 | 673.90     |        | 673.90  |
| 78 | 0  | T17565-31040 SUPPORT, EXHAUST <i>?</i>      | 1.00 | 49.40      |        | 49.40   |
| 79 | 1  | T85211-37251 ARM, FR WIPER, RH <i>out</i>   | 1.00 | 167.70     |        | 167.70  |
| 80 | 2  | T85221-37251 ARM, FR WIPER, LH <i>?</i>     | 1.00 | 192.50     |        | 192.50  |
| 81 | 3  | T85154-37030 PACKING, FR WIPER <i>xnn</i>   | 2.00 | 30.10      |        | 60.20   |
| 82 | 4  | T85070-25120 MOTOR & BRACKET <i>?</i>       | 1.00 | 1065.20    |        | 1065.20 |
| 83 | 5  | T85292-13010 CAP, WIPER ARM HEAD <i>xnn</i> | 2.00 | 14.50      |        | 29.00   |
| 84 | 6  | T87905-37123 ARM SUB-ASSY, OUTER <i>scr</i> | 1.00 | 720.70     |        | 720.70  |
| 85 | 7  | T51701-37360 BRACKET SUB-ASSY, <i>bt</i>    | 1.00 | 0.00       |        |         |
| 86 | 8  | T51702-37100 BRACKET SUB-ASSY, <i>bt</i>    | 1.00 | 845.40     |        | 845.40  |
| 87 | 9  | T52211-37010 SPACER, CAB FR <i>?</i>        | 2.00 | 70.10      |        | 140.20  |
| 88 | 0  | T54915-37230 SPRING, TILT CAB, <i>?</i>     | 1.00 | 449.10     |        | 449.10  |
| 89 | 1  | T54801-25130 TUBE SUB-ASSY, TILT <i>4</i>   | 1.00 | 845.40     |        | 845.40  |
| 90 | 2  | T90109-14013 BOLT <i>?</i>                  | 2.00 | 19.00      |        | 38.00   |
| 91 | 3  | T90101-14079 BOLT, HEXAGON <i>?</i>         | 4.00 | 16.70      |        | 66.80   |

| For & on behalf of                | Customer's Signature                  | Charge Summary    | Total      |
|-----------------------------------|---------------------------------------|-------------------|------------|
| Borneo Motors (Singapore) Pte Ltd | Please acknowledge receipt of vehicle | Parts             | Less       |
|                                   |                                       | Labour            |            |
|                                   |                                       | Sublet            | Amount Due |
|                                   |                                       | Lubrication/Fluid |            |
|                                   |                                       | Others            |            |



Reg No. : 196700086Z  
 ST Reg No. : MR-8500000-9  
 No. 2 PANDAN CRESCENT  
 SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

| Account Details                                                                                          | Account No.                 | Customer Details                                                                           |
|----------------------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------------------------|
| o Insurance Pte Ltd<br>emasek Boulevard<br>-01 Suntec Tower Five<br>gapore 038985<br>: Motor Claims Dept | S1000010 / ICNI3            | M/S Manikarnika Pte Ltd<br>77 High Street<br>#01-09A High Street Plaza<br>Singapore 179433 |
|                                                                                                          | Document No.<br>0           |                                                                                            |
|                                                                                                          | Document Date<br>09/02/2023 |                                                                                            |

| Year | Model   | Variant  | Reg. Date  | Reg. No. | Kilometers | Wip No. | Order No. / Remarks |
|------|---------|----------|------------|----------|------------|---------|---------------------|
| 2022 | GDY231R | TLMGV M1 | 20/12/2022 | YQ9072Y  | 0          | 20120   | 72/UL/YQ9072Y       |

| Chassis No.      | Engine No. | Terms | SA / Counter    | Vehicle In | Collected On         |
|------------------|------------|-------|-----------------|------------|----------------------|
| HHAGV4620K003138 | 1GD9034948 | 60    | Thomas Pang W T | --/--/---- | 0.00 --/--/---- 0.00 |

| Cd | Job/Parts Description                           | Qty  | Unit Price | Disc % | Amount  |
|----|-------------------------------------------------|------|------------|--------|---------|
| 4  | T54911-37160 ARM, TILT CAB SPRING ?             | 1.00 | 238.70     |        | 238.70  |
| 5  | T88718-25510 CLAMP, PIPING ?                    | 1.00 | 0.00       |        |         |
| 6  | T55448-37040 C0 COVER, OIL RESERVOIR TANK, RH ? | 1.00 | 32.70      |        | 32.70   |
| 7  | T87114-37010 COVER, HEATER ?                    | 1.00 | 178.90     |        | 178.90  |
| 8  | T55301-37090 C0 PANEL SUB-ASSY, <i>defect</i>   | 1.00 | 1210.70    |        | 1210.70 |
| 9  | T73970-37040 C0 AIR BAG ASSY, INSTR <i>acc</i>  | 1.00 | 5043.20    |        | 5043.20 |
| 0  | T45130-37170 C0 PAD ASSY, STEERING <i>acc</i>   | 1.00 | 3269.80    |        | 3269.80 |
| 1  | T73210-37550 B0 BELT ASSY, FR SEAT, <i>acc</i>  | 1.00 | 1194.70    |        | 1194.70 |
| 2  | T73210-37550 B0 BELT ASSY, FR SEAT, <i>acc</i>  | 1.00 | 1194.70    |        | 1194.70 |
| 3  | T89970-37020 SENSOR ASSY, AIR <i>acc</i>        | 1.00 | 260.70     |        | 260.70  |
| 4  | T89170-25040 COMPUTER ASSY, AIR <i>acc</i>      | 1.00 | 2369.10    |        | 2369.10 |
| 5  | T84307-37020 CABLE SUB-ASSY, <i>acc</i>         | 1.00 | 1282.90    |        | 1282.90 |
| 6  | T55330-37210 REINFORCEMENT ASSY, ?              | 1.00 | 753.00     |        | 753.00  |

*Paul*  
*Hp 90010068*  
*16 days*  
*P/P*  
*13/02/23 @ 1420*  
*EXCESS: TBA*  
*Revers*  
*Resy before print*

|                                                     |                                       |                                                                                               |            |           |
|-----------------------------------------------------|---------------------------------------|-----------------------------------------------------------------------------------------------|------------|-----------|
| & on behalf of<br>Borneo Motors (Singapore) Pte Ltd | Customer's Signature                  | Charge Summary                                                                                | Total      | 62,009.98 |
|                                                     | Please acknowledge receipt of vehicle | Parts 40,388.70<br>Labour 21,361.28<br>Sublet 260.00<br>Lubrication/Fluid 0.00<br>Others 0.00 | GST 8.00%  | 4,960.80  |
|                                                     |                                       |                                                                                               | Less       | 0.00      |
|                                                     |                                       |                                                                                               | Amount Due | 66,970.78 |