

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

**CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**

3 Anson Road #16-00  
 Springleaf Tower  
 Singapore 079909  
 Tel : 6389 - 6111  
 Fax : 6224 - 7478 / 7175

*Xiao Chen.*

**Quotation**  
 DATE : 03.04.2023  
 VEH NO : SMU2147H  
 MODEL : Hyundai Accent  
 D O A : 08.02.2023  
 YR REF : SMN8309E

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SMU2147H (HYUNDAI ACCENT)**

| <u>Item</u> | <u>Description</u>                              | <u>Qty</u> | <u>Amt</u>         |
|-------------|---|------------|--------------------|
| <b>NO</b>   | <b>LIST ITEMS</b>                               |            |                    |
| 1           | Rear Bumper <i>Delud</i>                        | 1          | 545.30 ✓           |
| 2           | Rear Bumper Side Holder - LH & RH <i>the nu</i> | 2          | 71.20 +            |
| 3           | Rear Bumper Reflector - LH & RH <i>the nu</i>   | 2          | 191.00 +           |
| 4           | Rear Bumper Reinforcement <i>Delud</i>          | 1          | 390.80 ✓           |
| 5           | Rear Bumper Bracket <i>the nu</i>               | 5          | 90.00 +            |
| 6           | Reverse Sensor <i>2 pieces delud</i>            | 4          | 740.40 - 370.20    |
| 7           | Reverse Sensor Holder <i>the nu</i>             | 4          | 100.00 ✓           |
| 8           | Taillamp - LH & RH <i>the nu</i>                | 2          | 776.40 +           |
|             |   |            | <u>\$ 2,905.10</u> |
|             | Less 20%  |            | <u>(581.02)</u>    |
|             |   |            | <u>\$ 2,324.08</u> |
|             | <b>S/NETT ITEMS</b>                             |            | <i>30</i>          |
| 1           | Rear Bumper Clips <i>the nu</i>                 | 1 set      | 30.00 ✓            |
|             | Total parts                                     |            | <u>\$ 2,354.08</u> |

**LABOUR CHARGE**

|   |  |    |                  |
|---|--|----|------------------|
| 1 | To knocking out rear portion & renew above parts | \$ | 400.00 <i>2w</i> |
| 2 | To putty & spray up paint works                  | \$ | 500.00 <i>2w</i> |
| 3 | To check wiring                                  | \$ | 50.00 <i>3w</i>  |
| 4 | To remove reverse sensor                         | \$ | 100.00 <i>50</i> |
|   | Total Labour                                     | \$ | <u>1,050.00</u>  |

**RE : ESTIMATE FOR ACCIDENT REPAIR SMU2147H (HYUNDAI ACCENT)**

**Grand Total**

**\$ 3,404.08**

**GST Will be reflected in the final bills**

**NOTE : -**

**PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.**

*total: 1635.04*

*L/S : 1.31c*

*02 Days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: