



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI22004395/Dqp3e2-1 Date: 22/03/2023 Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YQ 2278S	Veh. Inspected	SJK 5777H	
Policy No.	DMCVSNA00119112101	Coverage (\$)	0.00	
Claim No.	SNM22D203084/C02	Excess (\$)	0.00	
Assign From	ADELINE CHNG	Assign Date	08/02/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN SHARAN 2.0	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WVWZZZ7NZJV039095	Colour	GREY	
Odometer	91355 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/50 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	05/05/2022	Inspection Date	09/05/2022	
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	