

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS4/AIS23001492/AQY3E2
Date: 12/05/2023**REFERENCE**Insured/Claimant: Iskandar Bin Abdul Rani Policy No: SP2003475490
Date of Loss: 06/01/2023 Nature of Claim: OD Claim No: 202332004317**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLG8067B**
Make & Model: VOLKSWAGEN SCIROCCO, 1.4 L (A) Engine No: CAV150000
Reg. Date: 08/02/2010 (Man. Year: 2009) Chassis No: WVWZZZ13ZAV427617
Colour: Grey Odometer: 0 km
Engine Capacity: 1390 cc
Market Value/New Car Price: S\$67,000.00
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes**CONDITION OF TYRES**Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Nexen 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Nexen 6 mm Rear Right Side: Goodyear 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	500.00	500.00	0.00	0.00
Nett Amount (S\$)	-500.00	-500.00	0.00	0.00

INSPECTIONDate of Assignment: 13/02/2023 Present Location: Success United Pte Ltd (HQ)
Success United Pte Ltd (HQ)
Date Inspected: 13/02/2023 Inspected At: 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921
Estimated Period of Repair: 0.0 days**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$67,000.00
OMV :	\$23,891.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$31,976.00
COE Rebate (2) :	\$22,030.00
Total Rebate (1) + (2) = :	\$22,030.00

The total amount incurred will be Market Value \$67,000.00 minus Total Rebate \$22,030.00 = \$44,970.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 May 2023)

Parts: 144 VOLKSWAGEN SCIROCCO 1.4 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG8067B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >