



Your Ref : 202332004317

Date: 12th Dec 2022

Our Ref : CS4/AIS23001492/Aqy3e2

M/s Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLG 8067B
ACCIDENT ON 06/01/2023**

Instruction was received to inspect the vehicle Reg. No. SLG 8067B. The inspection was conducted on 13/02/2023 at the premises of M/s Success United Pte Ltd, 2 Kaki Bukit Ave 2 #01-33 Kaki Bukit Autohub, Singapore 417921.

The following vehicle information was recorded:

Registration Number	: SLG 8067B
Make/Model	: Volkswagen Scirocco 1.4L AT TSI 1372Q5
Year of Registration	: 2010
Body Colour	: Grey
Chassis Number	: WWZZZ13ZAV427617
Engine Capacity	: 1390 cc
Speedometer Reading	: Not Available

The vehicle sustained damages at the front, rear o/s portion and undercarriage. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	67,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	22,030.00)
Nett Liability	S\$	<u>44,970.00</u>
		=====

Vehicle Inspected By:



ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.