

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 14 Feb 2023

**Preliminary Advice**

Vehicle No	: SLG8067B	Accident Date	: 06/01/2023
Make	: VOLKSWAGEN SCIROCCO	Policy No.	: SP2003475490
Assignment Date	: 13/02/2023	Excess	: S\$500.00
Date of Inspection	: 13/02/2023	Est. Duration of Repair	: 0
Inspection At	: SUCCESS UNITED PTE LTD (HQ) 2 KAKI BUKIT AVE 2 #01-33, KAKI BUKIT AUTOHUB SINGAPORE 417921		

**Point of Impact / General Description of Damages**

The vehicle sustained damages at the front, rear portion, o/s body & undercarriage.

Repairer's Estimate (Gross)	:S\$	NOT READY
Revised Amount	:S\$	0.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	22,030.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,970.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : SUGGEST TO DO INVESTIGATION DUE TO MODIFICATION FOUND.