



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg

Co. / GST Reg: 200402570G

03 May 2023

Dear Sir / Madam,

Recommend Total Loss for Vehicle SLG8067B

The above said vehicle was involved in an accident on 06/01/2023 and the car was towed to our workshop on 10/02/2023 for an Own Damage claim as it is not driveable.

After we checked, the gearbox housing for this vehicle was spoiled and need to replace a new entire gearbox housing. As we get the quotation price from suppliers, the cost for a new gearbox housing is \$62,000 which the price is higher then the repair limit. Besides, we also asked used part suppliers, they also did not have any used gearbox housing for this vehicle.

Therefore, we recommend that this vehicle be approved as total loss.

Thank you.

Yours sincerely,



Anthony Soon Han Tiong
Operation Manager