





55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0154/2023/AB  
**DATE** : 7-Feb-23  
**WIP** : 62108

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/02/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Motor Claims Dept  
**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR YEO KAI KIAT KELLY  
**ADDRESS** : BLK 525 HOUGANG AVE 6  
#01-181  
SINGAPORE 822217  
**TELEPHONE** : HP +65 91881014  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7220039816  
**VEHICLE NO** : **SMA 1979 K**  
**MODEL CODE** : AUDI A3 SPORTBACK 1.5 TFSI  
**MODEL YEAR** : 30/11/2021  
**ENGINE NO** : DFY 302010  
**CHASSIS NO** : WAUZZZGY4NA013698  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 27-Jan-23  
**PLACE OF ACCIDENT** : BEF PUNGGOL ROAD,SINGAPORE



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 1979 K**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$	480.00	✓
2	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$	1,050.00	500
3	TO RESPRAY FRONT BUMPER	\$	900.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 2,622.00</b>	

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 1979 K**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,778.00	<i>de</i>
2	FRONT BUMPER FIXING PARTS	1	\$ 307.00	X
3	FRONT BUMPER BRACKET - LH / RH	2	\$ 68.00	X
4	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 274.00	?
5	FRONT BUMPER LOWER GRILLE - CENTRE	1	\$ 458.00	X
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 281.00	X
7	FRONT BUMPER SPOILER	1	\$ 345.00	?
8	FRONT BUMPER COVER TRIM - LH / RH	2	\$ 220.00	X
9	FRONT BUMPER AIR GRILLE - LH / RH	2	\$ 361.00	X
10	FRONT BUMPER AIR GRILLE SENSOR SUPPORT - LH / RH	2	\$ 92.00	X
11	FRONT RADIATOR GRILLE	1	\$ 1,167.00	X
12	FRONT RADIATOR GRILLE CLOSING ELEMENT - CENTER	1	\$ 223.00	X
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 127.00	X
14	FRONT BUMPER REINFORCEMENT	1	\$ 793.00	X
15	FRONT BUMPER REINFORCEMENT BRACKET - LH / RH	2	\$ 21.00	X
16	FRONT BUMPER TOP COVER	1	\$ 94.00	X
17	CAUTION STICKER	1	\$ 17.00	X
18	STICKER FOR AIR CONDITONER	1	\$ 9.00	X
19	TEMPERATURE SENSOR BRACKET	1	\$ 22.00	X
20	FRONT RADIATOR SEAL - RH	1	\$ 15.00	X
21	FRONT RADIATOR AIR GUIDE- LH / RH	2	\$ 90.00	X
22	FRONT RADIATOR AIR GUIDE - LOWER CENTRE	1	\$ 61.00	X
23	FRONT NO. PLATE	S/N	\$ 60.00	X
24	SUNDRIES	1	\$ 400.00	?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 7,283.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 2,622.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 9,905.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
 SURVEYED DATE :  
 AUTHORISED DATE :  
 EXCESS COST :  
 LIABILITY :  
 REMARKS :

Taufik 97495744 W/2/23040pm  
 Not insurance.  
 Ex: to be advise  
 03 days  
 Resurvey before paint  
 Taufik@khaut.com

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

JOHNNY BOO  
 BODY REPAIR MANAGER

ALLAN WU  
 CLAIMS CONSULTANT