

ASS. REC. BY: R. Paul

REF:

27fw

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNF 9678Mat Workshop m/s Premiumof ALCANTARAInsured: AK

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: TBD

(Client's Record)

Make of Veh: _____

(Policy Condition)

2pr

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 229k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNF 9678M Yr Regn: 2022 / JulType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A6 Design 2.0 TFSI c.c. 1984Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 15235 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAAU 222F21MN09595Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 225/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 04/02/23 D.O.I. 10/02/23Survey held at PremiumDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 91K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

) \$ + RS. \$ _____

) Photos

) Others

Report Format: _____

Lum Sum / E.R. / C.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0161/2023/EQ
DATE : 9-Feb-23
WIP : 62589

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S PREMIUM AUTOMOBILES PTE LTD
ADDRESS : 55 UBI ROAD 1
SINGAPORE 408699
TELEPHONE : HP +65 66090293
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 0999993555-01/1220004602
VEHICLE NO : SNF 9678 M
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 30/6/2022
ENGINE NO : DKY 015955
CHASSIS NO : WAUZZZF21MN097595
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Feb-23
PLACE OF ACCIDENT : UPPER THOMSON ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 9678 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	?
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	500
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,200.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,072.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9678 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de-</i>	1	\$ 3,187.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$ 689.00	
3	FRONT BUMPER CLOSING ELEMENT - CENTER <i>X</i>	1	\$ 263.00	
4	FRONT BUMPER ADAPTER - LH / RH <i>?</i>	2	\$ 94.00	
5	FRONT BUMPER REINFORCEMENT - LH / RH <i>?</i>	2	\$ 264.00	
6	FRONT BUMPER GRILLE - LOWER CENTRE <i>X</i>	1	\$ 181.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER <i>X</i>	1	\$ 248.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>?</i>	2	\$ 1,026.00	
9	FRONT BUMPER AIR GUIDE - LH / RH <i>?</i>	2	\$ 78.00	
10	FRONT BUMPER AIR GUIDE - LH / RH <i>?</i>	2	\$ 62.00	
11	RADIATOR GRILLE <i>cm</i>	1	\$ 2,603.00	
12	RADIATOR GRILLE COVER - CENTER <i>?</i>	1	\$ 65.00	
13	RADIATOR GRILLE COVER CAP <i>?</i>	1	\$ 59.00	
14	RADIATOR GRILLE BRACKET <i>?</i>	1	\$ 111.00	
15	FRONT "360" CAMERA <i>X</i>	1	\$ 1,115.00	
16	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 267.00	
17	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 1,140.00	
18	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ 71.00	
19	FRONT BUMPER BRACKET - LH / RH <i>?</i>	2	\$ 130.00	
20	FRONT BUMPER TOP COVER <i>de-</i>	1	\$ 149.00	
SUB TOTAL SPARE PARTS		:	\$ 11,802.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9678 M

S/N	PARTS DESCRIPTION	DAMAGED PARTS & PRICES			REMARKS
		QTY	S/NETT		
21	FRONT BUMPER GUIDE SECTION - LH / RH ?	2	\$	106.00	
22	AIR CONDITIONER STICKER X	1	\$	36.00	
23	CAUTION SIGN STICKER X	1	\$	17.00	
24	FRONT PARKING AID SENSOR - INNER / OUTER X	2	\$	598.00	
25	FRONT PARKING AID SEAL RING X	4	\$	11.00	
26	FRONT BUMPER WIRING SET ?	1	\$	648.00	
27	HORN LOW TONE - LH X	1	\$	244.00	
28	HORN HIGH TONE - RH X	1	\$	157.00	
29	HORN BRACKET - LH / RH X	2	\$	112.00	
30	BONNET X	1	\$	5,971.00	
31	BONNET IMPACT PROTECTION - CENTER / LH / RH X	3	\$	99.00	
32	BONNET STRIKER - LH / RH X	2	\$	260.00	
33	BONNET LOCK WITH MICRO-SWITCH - LH / RH X	2	\$	488.00	
34	BONNET RELEASE ELEMENT X	1	\$	69.00	
35	BONNET RELEASE LEVER X	1	\$	16.00	
36	BONNET BOWDEN CABLE - CENTER X	1	\$	67.00	
37	BONNET RELEASE CABLE COVER X	1	\$	12.00	
38	HEADLIGHT MOUNTING - LH / RH ?	2	\$	280.00	
39	HEADLIGHT - LH / RH ?	2	\$	19,424.00	
40	LIFT CYLINDER - LH / RH X	2	\$	460.00	
SUB TOTAL SPARE PARTS		:	\$	29,075.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9678 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LIFT CYLINDER BRACKET - LH / RH X	2	\$ 16.00	
42	LIFT CYLINDER HOSE X	1	\$ 208.00	
43	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 27.00	
44	RADIATOR AIR GUIDE - LH / RH ?	2	\$ 100.00	
45	RADIATOR AIR GUIDE - UPPER / LOWER ?	2	\$ 78.00	
46	FRONT WHEEL HOUSING LINER - LH / RH X	2	\$ 644.00	
47	FRONT WHEEL SPOILER - LH / RH X	2	\$ 392.00	
48	FRONT NUMBER PLATE Lt- ✓	S/N	\$ 60.00	
49	SUNDRIES ?		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 42,802.00	
TOTAL LABOUR CHARGES		:	\$ 6,072.00	
GRAND TOTAL		:	\$ 48,874.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: *Ram - Hg 9001068*
: *10/02/23 @ 1400*
: *3 days*
: *EXCESS: 700*
: *Revers*
: *Res before paint*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

Audi A6 Mild Hybrid 2.0A TFSI S-tronic Design

Overview Financial Accessories Similar Research Photos Map

Price	\$229,800		
Depreciation ⓘ	\$21,830 /yr View models with similar depre	Reg Date	24-Jun-2022 (9yrs 4mths 11days COE left)
Mileage	10,000 km	Manufactured ⓘ	2021
Road Tax ⓘ	\$1,194 /yr	Transmission	Auto
Dereg Value ⓘ	\$137,263 as of today (change)	Fuel Type	Petrol-Electric
COE ⓘ	\$106,001	OMV ⓘ	\$41,876
Engine Cap	1,984 cc	ARF ⓘ	\$50,627
Curb Weight ⓘ	1,680 kg	Power	140.0 kW (187 bhp)
Type of Vehicle	Luxury Sedan	No. of Owners ⓘ	1

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	271W

Vehicle Details

Vehicle No.:	SNF9678M
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2023
Vehicle Make:	AUDI
Vehicle Model:	A6 DESIGN 2.0 TFSI (140 KW)
Primary Colour:	Grey
Manufacturing Year:	2021
Engine No.:	DKY015955
Chassis No.:	WAUZZZF21MN097595
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$41,905.00
Original Registration Date:	30 Jun 2022
First Registration Date:	30 Jun 2022
Transfer Count:	0
Actual ARF Paid:	\$50,667.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2032
PARF Rebate Amount:	\$38,000.00

Intended COE Rebate Details

COE Expiry Date:	29 Jun 2032
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$106,001.00
COE Rebate Amount:	\$99,434.00
Total Rebate Amount:	\$137,434.00