

# AFORT TRANSPORTATION PTE LTD

## PAIR ESTIMATE

Vehicle No. : SHD7305J

Date: 06.02.2023

Make : HYUNDAI

Insurance: INCOME

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	\$276.20
2	REAR BUMPER SIDE BRACKET LH RH		\$55.80	\$111.60
1	ANTENNA SMARTKEY			\$40.50
1	REAR BUMPER FOG LAMP			\$201.50
1	REAR PANEL GARNISH			\$346.80
1	REAR PANEL			\$532.00
			932.65	
	<b>SUB TOTAL</b>			\$2,836.05
	<b>LESS 20%</b>		746.12	\$567.21
	<b>DISCOUNTED TOTAL</b>			<b>\$2,268.84</b>
	REAR NUMBER PLATE WITH TRIM COVER		50	\$50.00
	REAR BUMPER REVERSE SENSOR		180	\$180.00
		NETT	162	<b>\$230.00</b>
	<b>Labour Charge</b>		212	
	PANEL BEATING			\$400.00
	SPRAY PAINTING CHARGE			\$300.00
	CHK ALL LIGHTING/ WIRING			\$60.00
	TUFF KOTE			\$60.00
	REMOVE/REFIX REVERSE SENSOR		660	\$80.00
	<b>TOTAL LABOUR</b>		1618.12	<b>\$900.00</b>
	<b>ESTIMATE TOTAL</b>		2158.12	<b>\$3,398.84</b>
			02 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanji 97495749  
 WP 6/2/23 430pm  
 L/S Resurvey after repair  
 Tanji (Kharko) 06m  
 02 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: