

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SMB1329G


OUR REF.: SNG621E

TO: FIRST CAPITAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

ESTIMATE FOR VEHICLE NO.: SNG621E



DATE: 17/2/2023

FROM: Lee Shirley

FAX: 64525333

CONTACT: 86865188

MAKE & MODEL: MERCEDES E63S AMG

CHASSIS NO.: W1K2132892A974997

ENGINE NO.: 17798060143142

YEAR MADE: 2021

ACCIDENT DATE: 11 February 2023

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	REAR FENDER RH		1	\$ 500 3,400.00 R+
2	REAR FENDER INNER SHIELD RH		1	\$ 210.00 7nn
3	REAR FENDER INNER SHIELD CLIP		10	\$ 2200 80.00 7nn
4	REAR BUMPER		1	\$ 500 2,800.00 X SCR
5	REAR BUMPER SIDE RETAINER RH		1	\$ 120.00 7nn
6	REAR BUMPER SENSOR		1	\$ 80.00 7nn
7	REAR BUMPER CLIP		10	\$ 100 100.00 30
8	TAIL LAMP RH		1	\$ 850.00 7nn
9	TYRE RIM REAR RH		1	\$ 5000 5,020.00 ✓ 1200
TOTAL:				\$ 12,660.00
LESS 10%:				\$ (1,266.00)
PARTS TOTAL:				\$ 11,394.00

SPECIAL NETT

WINDSCREEN SEALANT

BODY SEALANT

1 \$ NN X 50.00 sc

1 \$ NN X 50.00 sc

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS

\$ 400 1,600.00

TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS

\$ 200.00 X

TO REMOVE & REFIT QUARTER GLASS RH

\$ 100.00 ✓ 100

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

\$ 250.00 X

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ 400 1,000.00

TOTAL: \$ 14,644.00

7% GST: \$ 1,025.08

GRAND TOTAL: \$ 15,669.08

Akid Kamel (LKK)

DOS

8700 5631

17/02/2023

03 days

1509hrs

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
T 6262 8888 F 6452 5333
COMPANY REG. NO. 200204110W

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SMB1329G


OUR REF.: SNG621E

TO: FIRST CAPITAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

FINALISE FOR VEHICLE NO.: SNG621E



DATE: 15/5/2023

FROM: Lee Shirley

FAX: 64525333

CONTACT: 86865188

MAKE & MODEL: MERCEDES E63S AMG

CHASSIS NO.: W1K2132892A974997

ENGINE NO.: 17798060143142

YEAR MADE: 2021

ACCIDENT DATE: 11 February 2023

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	REAR FENDER RH		1	REPAIR
2	REAR BUMPER		1	\$ 2200 2,800.00
3	REAR BUMPER CLIP		10	\$ 30.00
4	TYRE RIM REAR RH		1	\$ 3492.69 5,020.00
TOTAL:				\$ 7,850.00
LESS 10%:				\$ (785.00)
PARTS TOTAL:				\$ 7,065.00

SPECIAL NETT

SUPP Pirelli P Zero 265/35R20 (A)

1 \$ 294 701° 420.00 cut

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS

\$ 400.00

TO REMOVE & REFIT QUARTER GLASS RH

\$ 100.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ 400.00

SUPP TO REMOVE, RENEW & REFIT REAR RH TYRE (A)

\$ 30.00 ✓

TOTAL: \$ 8,385.00

7% GST: \$ 586.95

GRAND TOTAL: \$ 8,971.95

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W