

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SMB1329G


OUR REF.: SNG621E

TO: FIRST CAPITAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

FINALISE FOR VEHICLE NO.: SNG621E



DATE: 15/5/2023

FROM: Lee Shirley

FAX: 64525333

CONTACT: 86865188

MAKE & MODEL: MERCEDES E63S AMG

CHASSIS NO.: W1K2132892A974997

ENGINE NO.: 17798060143142

YEAR MADE: 2021

ACCIDENT DATE: 11 February 2023

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	REAR FENDER RH		1	REPAIR
2	REAR BUMPER		1	\$ 2200 2,800.00
3	REAR BUMPER CLIP		10	\$ 30.00
4	TYRE RIM REAR RH		1	\$ 3492.69 5,020.00
TOTAL:				\$ 7,850.00
LESS 10%:				\$ (785.00)
PARTS TOTAL:				\$ 7,065.00

SPECIAL NETT

SUPP Pirelli P Zero 265/35R20 (A)

1 \$ 294 701° 420.00 cut

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS

\$ 400.00

TO REMOVE & REFIT QUARTER GLASS RH

\$ 100.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ 400.00

SUPP TO REMOVE, RENEW & REFIT REAR RH TYRE (A)

\$ 30.00 ✓

TOTAL: \$ 8,385.00

7% GST: \$ 586.95

GRAND TOTAL: \$ 8,971.95

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W