



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CS/CTI23001541/p3

Date: 13/02/2023

Code: CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLC 3330U
Policy No. DMPCSNW00178682200	Coverage (\$)	0.00
Claim No. SNM23D200912/C01	Excess (\$)	1,000.00
Assign From ALFRED TOH	Assign Date	13/02/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date 03/02/2023	Inspection Date
Survey held at 6 MARSILING LANE	
Repairer CENTURY MOTORS PTE LTD	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.